

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12299

Date In: 01 JUL 25 Author: DLUCAS
Promised Date: 16 SEP 25 Stock No: 11384
: Year: 2025
Customer Name: 17737 - ZIMMERMANN, CH Manufacturer: FOREST RIVER
Address: 3764 S CHEROKEE WAY Brand: FLAGSTAFF SUPER-LITE T
: MILWAUKEE, WI Model: 29RLBS
Postal/Zip: 53221 Miles/Hrs: 0
Phone#(res): 414-687-6589 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: CHRISTOPHERZIMMERMANN8 Tag#: DB: 8/6
Purchased Date: 02 JUN 25 :
Delivery Date: 24 JUN 25 :
InService Date: :
Serial#: 4X4TFLL25SZ196858 :

Job # Description JOB INFORMATION Type Bill To

SC CUSTOMER REQUESTS SERVICE CALL TO SANDY SHORES I SEP POLIC
TUBING RESORT #39 N4206 26TH AVE MAUSTON, WI 53948
1 COMPLAINT: CUSTOMER REQUEST HITCH BE INSTALLED TO I SEP POLIC
VEHICLE ONSITE (UNDERSTANDS MAY NOT BE
PERFECT INSTALL DUE TO NOT BEING ON
LEVEL GROUND POTENTIALLY)
CAUSE: hitched install
CORRECTION: hitch installed on truck and saddle are
secured to framework and leveled
2 COMPLAINT: CUSTOMER STATES SHOWER MEISER IS NOT W 1021 FORES
WORKING RIGHT DOESNT DO WHAT ITS
SUPPOSED TO WITH WATER FLOW
CAUSE: misunderstanding on how to use shower
miser
CORRECTION: explain how to use shower miser now ok
.20 HOURS OF LABOR
3 COMPLAINT: CUSTOMER STATES SLIDE TOPPER IS NOT W 1021 FORES
TAUGHT ENOUGH IS VISIBLE AND IS ALLOWING
WATER TO POOL
CAUSE: adjustments to slide topper
CORRECTION: on door side slide topper adjustments
made now ok
4 COMPLAINT: CUSTOMER STATES THE MALE END OF THE W 1021 FORES
QUICK CONNECT HOSE THAT SNAPS IN TO
QUICK CONNECT SEEMS DAMAGED AND WONT GO
INTO QUICK CONNECT
CAUSE: make lp quick disconnect is damaged
CORRECTION: delivery of complete new griddle

Continued on page 2

Work Order : 12299

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
5      COMPLAINT:  CUSTOMER STATES WHEN TURNING SWITCH TO  W   1021  FORES
      MAIN PANEL, LIGHTS IN BEDROOM ARE
      GETTING DIMMER AND DIMMER
      CAUSE:      customer didn't know they can dim the
      bedroom lights by holding the mum switch

      CORRECTION: no issues
6      BRING REDUCER SLEEVE SET AS CUSTOMER BOUGHT NEW      E   17737  ZIMME
      TRUCK AND HITCH DOES NOT FIT IN NEW SHANK
*****
```

```
*****
Job # Part No  Description                PARTS                Bill to  Qty  Price  Total
*****
4      822045744 GRIDDLE - PFL: OUTDOOR GRID W-1021      1   139.43  139.43
6      822045408 REDUCER SLEEVE SET-REDUCES  E-17737      1    41.66   41.66
*****
```

```
*****
Job#  Lab Code  Description                LABOUR    Mech Bill to  Hrs  Rate  Total
*****
1  Z991      MISC CODE (NTERNAL)      JS  I-SEP      0.50  70.00  35.00
2  WARR      MANUFACTURER WARRANTY    JS  W-1021     0.25  140.00  35.00
3  WARR      MANUFACTURER WARRANTY    JS  W-1021     0.60  140.00  84.00
4  WARR      MANUFACTURER WARRANTY    JS  W-1021     0.03  140.00   4.20
1  Z991      MISC CODE (NTERNAL)      JS  I-SEP      1.24  70.00  86.80
4  WARR      MANUFACTURER WARRANTY    JS  W-1021     0.47  140.00  65.80
5  Z990      MISC LABOUR CODE (EXTE JS  W-1021     0.02  140.00   2.80
*****
```

```
*****
Job #  Excode  Description                EXTRAS                bill to  Qty  Price  Total
*****
SC  SC      SERVICE CALL                I-SEP      42.00  3.75  157.50
6  SSE      SHOP SUPPLIES - EXTERNAL    E-17737     1.00  0.00   0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
E  17737      41.66   0.00   0.00   0.00   2.30   43.96
I  SEP       0.00  121.80   0.00  157.50   0.00  279.30
W  1021     139.43  191.80   0.00   0.00   0.00  331.23

      Totals      181.09  313.60   0.00  157.50   2.30  654.49
*****
```

&k2S
&k0S