

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2390192
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUGC2T4024999
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$140.00	ITEM #	PUT18BHCE-1
OWNER INFORMATION		DEALER RO #	12301
		CLAIM START DATE	08/04/2025
		CLAIM END DATE	08/07/2025

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-95-24-00-000947	Operational Description Dinette Cushions - Interior/Dinette/Repair/No Tread Code		
	Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2025-08-04 21:17:39 :: Complaint: Putty squished into the dinette cushions. Cause: From manufacturer. Correction: Used quick solve to remove the putty stains on cushions.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$70.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$70.00
	Notes			

Labor

Line# 2	Operation Code 30-100-01-00-001042	Operational Description Mirror or Glass From Cabinet Door Frame - Interior/Cabinetry/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2025-08-04 21:19:19 :: Complaint: Bathroom mirror was laying on the bathroom floor. It fell off the wall holders, cracked and the tape gave way. Cause: Fell off wall. Correction: Added double stick tape to back of the mirror, installed new plastic holds then cleaned off foam tape from floor where the tap has stuck from back of mirror to floor. Additional Note : greeneway@dealer-advisors.com, 2025-08-04 21:19:50 :: Did not replace- only repaired. Additional Note : greeneway@dealer-advisors.com, 2025-08-04 21:21:27 :: The mirror didn't crack- the holders cracked.			
Model#	Dlr Sub Hrs	0.75	Sub Labor Amt	\$105.00
Serial#	Appr Hrs	0.75	Appr Labor Amt	\$105.00
	Notes			

Labor

Line# 3	Operation Code 30-102-12-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2025-08-04 21:20:29 :: Complaint: The bottom bunk has loose trim. Cause: Trim is loose from factory. Correction: Used pin nailer to secure.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$42.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$14.00
	Notes flat rate to secure			

Submitted	Labor Amt	\$217.00	Approved	Labor Amt	\$189.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00

Total \$217.00

Total \$189.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.