

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12307

|                 |                     |                 |                   |
|-----------------|---------------------|-----------------|-------------------|
| Date In:        | 03 JUL 25           | Author:         | KOTT              |
| Promised Date:  | 12 AUG 25           | Stock No:       | 11327             |
| :               | :                   | Year:           | 2025              |
| Customer Name:  | 1021 - FOREST RIVER | Manufacturer:   | FOREST RIVER      |
| Address:        | 21815 NETWORK PLACE | Brand:          | PUMA TT           |
| :               | CHICAGO, IL         | Model:          | 337BH             |
| Postal/Zip:     | 60673-1218          | Miles/Hrs:      | 0                 |
| Phone#(res):    | 219-534-3167        | Exterior Color: | :                 |
| Phone#(bus):    | 219-534-3167        | Unit Type:      | TT-TRAVEL TRAILER |
| Cell Phone:     | :                   | License#:       | :                 |
| Email:          | NONE                | Tag#:           | DB: 7/8           |
| Purchased Date: | 24 APR 25           | :               | :                 |
| Delivery Date:  | 09 MAY 25           | :               | :                 |
| InService Date: | :                   | :               | :                 |
| Serial#:        | 5ZT2PUZB9S4023139   | :               | :                 |

\*\*\*\*\*

| Job # | Description | JOB INFORMATION                            | Type | Bill To |
|-------|-------------|--------------------------------------------|------|---------|
| 1     | COMPLAINT:  | CUSTOMER STATES THAT THE REAR ENTRY DOOR W | 1021 | FORES   |
|       |             | IS VERY HARD TO CLOSE- CUSTOMER STATES     |      |         |
|       |             | THAT YOU HAVE TO SLAM IT TO GET IT TO      |      |         |
|       |             | CLOSE PROPERLY- WOULD LIKE TO HAVE         |      |         |
|       |             | LOOKED AT-                                 |      |         |
|       | CAUSE:      | The screen door was hitting the catch.     |      |         |
|       |             | I hit the screen door with a rubber        |      |         |
|       |             | mallet. Now it operates properly.          |      |         |
|       | CORRECTION: | Done.                                      |      |         |
| 2     | COMPLAINT:  | CUSTOMER STATES THAT THERE IS A BOWED W    | 1021 | FORES   |
|       |             | PANEL IN THE BEDROOM- IT IS DARK GRAY IN   |      |         |
|       |             | COLOR- IT IS BY THE DOOR JAM TO THE        |      |         |
|       |             | BEDROOM- NEED TO DIAGNOSE FOR WARRANTY     |      |         |
|       | CAUSE:      | Both of the plastic door jams are bowed    |      |         |
|       |             | out. I added a screw to the sections       |      |         |
|       |             | that were bowed.                           |      |         |
|       | CORRECTION: | Done.                                      |      |         |

\*\*\*\*\*

| Job# | Lab Code | Description           | LABOUR | Mech   | Bill to | Hrs  | Rate   | Total |
|------|----------|-----------------------|--------|--------|---------|------|--------|-------|
| 1    | WARR     | MANUFACTURER WARRANTY | JGK    | W-1021 |         | 0.50 | 140.00 | 70.00 |
| 2    | WARR     | MANUFACTURER WARRANTY | JGK    | W-1021 |         | 0.49 | 140.00 | 68.60 |
| 1    | WARR     | MANUFACTURER WARRANTY | JGK    | W-1021 |         | 0.00 | 140.00 | 0.00  |
| 2    | WARR     | MANUFACTURER WARRANTY | JGK    | W-1021 |         | 0.01 | 140.00 | 1.40  |

Continued on page 2

Work Order : 12307

\*\*\*\*\*

## BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax  | Total  |
|------|---------|-------|--------|--------|--------|------|--------|
| W    | 1021    | 0.00  | 140.00 | 0.00   | 0.00   | 0.00 | 140.00 |
|      | Totals  | 0.00  | 140.00 | 0.00   | 0.00   | 0.00 | 140.00 |

&k2S  
&k0S