

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12321

Date In: 08 JUL 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No:
: Year: 2023
Customer Name: 17233 - Race, John Manufacturer: GRAND DESIGN
Address: Unknown Brand: SOLITUDE
: Aura, IL Model: 310GK
Postal/Zip: IL Miles/Hrs:
Phone#(res): 708-491-5375 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: racej1775@gmail.com Tag#: emailed 8/8
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573FS3626PAA15181 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: recall for the steps. recall 25v-061 W 1020 GRAND
CAUSE: Interior steps recall. Recall is needed.
Recall. I could only install one bracket
because of the shoe storage.
CORRECTION: installed the brackets on the steps.
Done. COULD ONLY INSTALL ONE BRACKET DUE
TO THE SHOE BIN NOT HAVING A STEP LIP TO
INSTALL THE SCREWS FOR THE BRACKET.
REQUEST .50 HOURS OF LABOR
2 COMPLAINT: would like unit checked for the frame E 17233 Race
flex, there is gaping in the closet door
and cmr believes it is caused by frame
flex.
CAUSE: Check for frame flex.
CORRECTION: Flex is with in normal peramiters.
3 COMPLAINT: cmr would like to purchase and have E 17233 Race
installed a Gen Y executive Gooseneck.
CAUSE: Gooseneck hitch install.
CORRECTION: Removed original pin box then install
the gooseneck. Jess helped me.
1 COMPLAINT: CLOSET DOOR IS HANGING CROOKED. RIGHT E 17233 Race
HAND DOOR. WHERE WASHER AND DRYER PREP
IS.
CAUSE: Closet door for washer and dryer closet
is crooked. The lower portion of the
wall that the door mounts to is not
fastened very good to the floor so it
moves in travel. Would have to remove

Continued on page 2

Work Order : 12321

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                wall panel and resecure to the floor.
                1.5 labor.
CORRECTION:  Removed trimmings, then refasten bottom
                of wall back down to floor. Wall is more
                solid now.
```

```
*****
Job # Part No  Description                PARTS                Bill to  Qty  Price  Total
*****
WARR0 822093414 STEP TREAD ANGLE BRACKET 16 W-1020      1   11.36  11.36
WARR0 822061989 SCREW 8 X 3/4 RD WASHER QUA W-1020      9    0.55   4.95
3      GH-8056AL GEN-Y EXECUTIVE 5TH TO GOOS E-17233     1 1,905.53 1,905.53
```

```
*****
Job# Lab Code  Description                LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR TD W-1020      0.00 140.00  0.00
ARR01 Z992      MISC LABOUR CODE (WARR TD W-1020      0.02 140.00  2.80
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50 140.00  70.00
  2 Z990      MISC LABOUR CODE (EXTE TD E-17233     0.20 140.00  28.00
  3 RV4-7      GOOSENECK ADAPTER INST TD E-17233     1.25 140.00 175.00
  3 RV4-7      GOOSENECK ADAPTER INST TD E-17233     0.25 140.00  35.00
  1 Z990      MISC LABOUR CODE (EXTE TD E-17233     0.00 140.00  0.00
  1 Z990      MISC LABOUR CODE (EXTE TD E-17233     0.09 140.00 12.60
  1 Z990      MISC LABOUR CODE (EXTE TD E-17233     0.00 140.00  0.00
  1 Z990      FIX WALL JOIST          TD E-17233     1.50 140.00 210.00
```

```
*****
Job # Excode  Description                EXTRAS                bill to  Qty  Price  Total
*****
ARR01 FRT        FREIGHT                    W-1020      1.00 29.80  29.80
  2 SSE        SHOP SUPPLIES - EXTERNAL  E-17233     1.00 34.55  34.55
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
E  17233      1905.53  460.60   0.00   34.55 132.07 2,532.75
W  1020       16.31   72.80   0.00   29.80  0.00  118.91

Totals      1921.84  533.40   0.00   64.35 132.07 2,651.66
```

&k2S
&k0S