

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12342B

Date In:	17 JUL 25	Author:	KOTT
Promised Date:	25 DEC 25	Stock No:	11398
:	:	Year:	2025
Customer Name:	17772 - PETERSON, MELI	Manufacturer:	FOREST RIVER
Address:	N8801 RUNNING BEAR TRA	Brand:	PUMA CAMPING EDITION
:	NEW LISBON, WI	Model:	18BHCE
Postal/Zip:	53950	Miles/Hrs:	0
Phone#(res):	6085485336	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	mekayp72@gmail.com	Tag#:	:
Purchased Date:	09 JUL 25	:	:
Delivery Date:	16 JUL 25	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUGC4S4024260	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -bottom bunk wall has W    1021    FORES
        CAUSE:      Protruding staples
        CORRECTION: Used hammer to set staples REQUEST .30
                   HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - trim on the Slide      W    1021    FORES
        CAUSE:      To short of a cut
        CORRECTION: I used black silicone to fill the area ,
                   REQUEST .50 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 4 -air conditioner does W    1021    FORES
        CAUSE:      A ground wire had become disconnected
        CORRECTION: Reconnected the ground wire then ran AC
                   and it works as it should REQUEST .75
                   HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - the top bulb seal is W    1021    FORES
        CAUSE:      Mfg bulb seal not installed correctly
        CORRECTION: Reinstalled the bulb seal then I used
                   clear silicone to seal above the bulb
                   seal REQUEST .40 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 6 - the board for          W    1021    FORES
        CAUSE:      scwintek blinks 9 times indicating that
                   the hall power has a short to ground
        CORRECTION: Needed a reset
                   I unplugged both connections then
                   plugged them back in ,I then ran the
```

Continued on page 2

Work Order : 12342B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
slide in and out and no error code
appeared works as it should REQUEST .30
HOURS OF LABOR
WARR    COMPLAINT: WARRANTY REPAIR 7 - power wire that runs W    1021    FORES
under slide room is visable once room is
brought out
CAUSE:    It's excess cord
CORRECTION: Tucked beneath slide room REQUEST .50
HOURS OF LABOR
WARR    COMPLAINT: WARRANTY REPAIR 8 - the hole cut beneath W    1021    FORES
bed is very rough cut
CAUSE:    Very sharp wood shards left on wood and
paneling that the mfg built the bed
frame out of
CORRECTION: Used course sand paper to remove dnd
smooth so customers do not get large
slivers or any slivers when putting
things beneath the bed REQUEST .30 HOURS
OF LABOR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.30  140.00  42.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.20  140.00  28.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.00  140.00   0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.44  140.00  61.60
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.06  140.00   8.40
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.09  140.00  12.60
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.41  140.00  57.40
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00

```

```

*****
Job #  Excode    Description  EXTRAS      bill to  Qty  Price  Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1021  1.00   0.00   0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
W    1021          0.00   490.00   0.00   0.00   0.00   490.00
Totals          0.00   490.00   0.00   0.00   0.00   490.00

```

Continued on page 3

Work Order : 12342B

&k2S
&k0S