

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12347

Date In: 11 JUL 25 Author: MGRAY
Promised Date: 18 JUL 25 Stock No: 10045
: Year: 2021
Customer Name: 14542 - DALLMAN, GENE Manufacturer: GRAND DESIGN
Address: 4931 OCONNER RD Brand: SOLITUDE
: MAUSTON, WI Model: 310GK
Postal/Zip: 53948 Miles/Hrs:
Phone#(res): (715) 482-0156 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: GJDALLMAN@GMAIL.COM Tag#:
Purchased Date: 05 JAN 21 :
Delivery Date: 09 APR 21 :
InService Date: :
Serial#: 573FS3628MAA04145 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - recall for steps. W 1021 FORES
need to get recall number from Anna.
CAUSE: Manufacturer recall
CORRECTION: Installed recall kit for stair trees.
2steps. REQUEST .50 HOURS OF LABOR
2 COMPLAINT: there is a water leak in the unit. cmr E 14542 DALLM
states " i filled up the fresh water and
it leaked a little bit. was hooked up to
city water and when settled found that
the front compartment had a large puddle
of water in it". would like checked out
to see if we can find leak to get
fixed.THERE IS A HOSE GOING OUT TO THE
QUICK CONNECT WATER CONNECT BY THE ENTRY
DOOR DRIPPING. THEN HE WAS USING THE LOW
POINT DRAINS AND BLUE WILL NOT CLOSE
OFF.
CAUSE: QD sprayport on DS, fitting leaking.
When checked was hand tight. Tried to
tighten, threading on braided hose
fitting is bad, needs a new fitting.
CORRECTION: New fitting and seal installed. No more
leaking from back of QD.
1 COMPLAINT: CUSTOMER REQUESTS HAVING THE SLIDE OUTS E 14542 DALLM
INSPECTED TO SEE IF THEY NEED TO BE
LUBRICATED-
CAUSE: Request inspect slide hardware.
Inspected slide mechanisms, looked

Continued on page 2

Work Order : 12347

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                slightly rusty but is normal.
CORRECTION: Sprayed hydraulic slide rails with
              penetrative lube w/PTFE, should last a
              while. Working well, even schwintek in
              bedroom.
RI      COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF    I    PD    GOODW
              REPAIR IS NEEDED.
CAUSE:      Request roof inspection
CORRECTION: Both front corners need to get cleaned
              and touched up, two spots on the
              bathroom skylight as well,with dicor,
              otherwise looks fine, no further action
              necessary. Touch-ups complete.
3      COMPLAINT: CUSTOMER STATES THAT THEY CANT GET THE    E    14542  DALLM
              ENTRY DOOR TO LOCK- KEYS ARE ON THE
              BOARD- NEEDS TO BE DIAGNOSED-
CAUSE:      Unknown issue. Request diagnose entry
              door not locking. Used provided keys,
              works as designed.
CORRECTION: NPF
    
```

```

*****
Job # Part No   Description                PARTS    Bill to    Qty    Price    Total
*****
WARR0 822093414   STEP TREAD ANGLE BRACKET W-1021    2      7.38    14.76
WARR0 822061989   SCREW 8 X 3/4 RD WASHER W-1021    18     0.07    1.26
2     752324313754 1/2" BARB STRAIGHT ADAPT E-14542    1      5.42    5.42
2     742979164351 SINGLE 1/2" SWIVEL SEAL  E-14542    1      2.31    2.31
    
```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992    MISC LABOUR CODE (WARR RW W-1021    0.50   140.00   70.00
2     DIAG    DIAGNOSTICS                RW      E-14542  0.60   130.00   78.00
RI    Z991    PREFORM ROOF INSPECTIO RW      I-PD    0.21   70.00    14.70
1     Z990    MISC LABOUR CODE (EXTE RW E-14542  0.10   130.00   13.00
3     Z990    MISC LABOUR CODE (EXTE RW E-14542  0.20   130.00   26.00
2     DIAG    DIAGNOSTICS                RW      E-14542  0.90   130.00  117.00
RI    Z991    PREFORM ROOF INSPECTIO RW      I-PD    0.09   70.00    6.30
    
```

```

*****
Job # Excode Description                EXTRAS    bill to    Qty    Price    Total
*****
2     SSE     SHOP SUPPLIES - EXTERNAL E-14542    1.00   17.55   17.55
    
```

Continued on page 3

Work Order : 12347

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	14542	7.73	234.00	0.00	17.55	14.30	273.58
I	PD	0.00	21.00	0.00	0.00	0.00	21.00
W	1021	16.02	70.00	0.00	0.00	0.00	86.02
	Totals	23.75	325.00	0.00	17.55	14.30	380.60

&k2S

&k0S