

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12379B

Date In: 07 OCT 25 Author: KOTT  
Promised Date: 31 DEC 25 Stock No: 11459  
: Year: 2026  
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN  
Address: 8220 STATE HWY 13 SOUT Brand: REFLECTION 150 SERIES  
: WISCONSIN RAPIDS, WI Model: 270BN  
Postal/Zip: 54494 Miles/Hrs: 0  
Phone#(res): 800-758-2272 Exterior Color:  
Phone#(bus): Unit Type: FW-FIFTH WHEEL  
Cell Phone: License#:  
Email: NONE Tag#: DB: 10/9  
Purchased Date: :  
Delivery Date: :  
InService Date: :  
Serial#: 573FR312XT3353925 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 1 -leaking behind the W 1020 GRAND  
Nadus panel  
CAUSE: Was not tightened all the way  
CORRECTION: Tightened up the fitting REQUEST .20  
HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 2 -spray port in back of W 1020 GRAND  
camper is leaking  
CAUSE: 1019 MISSING PART  
CORRECTION: Put in the o-ring that was missing  
REQUEST .75 HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 3 cabinet doors need to W 1020 GRAND  
be adjusted in the bedroom  
CAUSE: 1018 POOR FITMENT  
CORRECTION: Readjusted cabinet doors, close, and  
lineup nice REQEUST .20 HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 4 -stain on Couch W 1020 GRAND  
CAUSE: Stain from manufacturer  
CORRECTION: Use quick solve clean the stain off  
REQUEST .20 HOURS  
WARR COMPLAINT: WARRANTY REPAIR 5 -scuffs and necks W 1020 GRAND  
throughout the unit  
CAUSE: Workers rubbing up against the wall  
CORRECTION: Clean scuffs and marks with quick solv  
REQUEST .30 HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 6 -AC on the front of W 1020 GRAND  
the unit blower motor is stuck  
CAUSE: Fan was not adjusted properly  
CORRECTION: Readjusted the fan now works properly

Continued on page 2

Work Order : 12379B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
request 1 hours of labor
WARR   COMPLAINT:  WARRANTY REPAIR 8 -damaged pin box       E    1000   GREEN
        CAUSE:      1004 ISSUE CAUSED BY driver
        CORRECTION: . WILL NEED TO R&R THE KING PIN WEDGE
    
```

```

*****
Job # Part No      Description           PARTS      Bill to   Qty    Price    Total
*****
WARR0 742979164351 SINGLE 1/2" SWIVEL SEAL  W-1020     1     1.91     1.91
WARR0 161128         NOVAFLEX PRO 10 OZ TRANS W-1020     1     9.28     9.28
WARR0 82201118         BUTYL TAPE 1/8"X1"X30' B W-1020     1    14.82    14.82
    
```

```

*****
Job# Lab Code  Description           LABOUR    Mech Bill to   Hrs    Rate    Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.50   140.00   70.00
ARR02 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.31   140.00   43.40
ARR02 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.19   140.00   26.60
ARR03 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.50   140.00   70.00
ARR04 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.50   140.00   70.00
ARR05 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.27   140.00   37.80
ARR05 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.23   140.00   32.20
ARR06 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.00   140.00    0.00
ARR06 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.00   140.00    0.00
ARR06 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.50   140.00   70.00
ARR06 Z992     MISC LABOUR CODE (WARR JL  W-1020     0.00   140.00    0.00
ARR08 Z992     MISC LABOUR CODE (WARR     E-1000     0.00   140.00    0.00
    
```

```

*****
Job # Excode      Description           EXTRAS      bill to   Qty    Price    Total
*****
ARR01 SSE         SHOP SUPPLIES - EXTERNAL W-1020     1.00    0.00    0.00
    
```

BILLINGS SUMMARY

```

Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1020          26.01    420.00    0.00     0.00    0.00    446.01
Totals          26.01    420.00    0.00     0.00    0.00    446.01
    
```

&k2S  
&k0S