

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12386B

Date In: 20 AUG 25 Author: DLUCAS  
Promised Date: 31 DEC 25 Stock No: 11408  
: Year: 2026  
Customer Name: 12979 - BURANT, MARIA Manufacturer: FOREST RIVER  
Address: 1546 ARBOR CREEK DRIVE Brand: PUMA DESTINATION  
: OAK CREEK, WI Model: 403LFT  
Postal/Zip: 53154 Miles/Hrs: 0  
Phone#(res): 414-507-8219 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: RMBURANT@GMAIL.COM Tag#: DB: 8/25  
Purchased Date: 11 JUN 25 :  
Delivery Date: 15 JUL 25 :  
InService Date: :  
Serial#: 4X4TPUS22TP106390 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
4 COMPLAINT: LEAK ON SLIDEOUT BY PATIO DOOR RIGHT W 1021 FORES  
SIDE OF SLIDE BY PATIO DOOR  
CAUSE: will need to try sealing the plastic  
inside corner with silicone also i think  
carpet on the wrong side of fascia board  
heavey down pours it get saturated may  
have to pull inside fascia wood off to  
reattach i think rubber cut to short on  
back side of fascia pics taken  
CORRECTION: so i used black non leveling laps  
sealant to seal all seams on corners box  
of them two spots thatvwas leaking i  
also removed the decorative fascia from  
slide and fast the carpet fot slide  
floor behind decorative wood so no water  
touches on both slides  
5 COMPLAINT: CUSTOMER STATES TWO UPPER WINDOWS MARKED W 1021 FORES  
WITH TAPE ARE TAKING WATER ON  
CAUSE: on off door side both windows above  
slide outs are leaking around the glass  
CORRECTION: remove the damage windows used butyl  
tape on framework of both windows and  
secured to camper i also used silicone  
around exterior framework the windows  
are sealed  
1 COMPLAINT: CUSTOMER STATES CARPET IS STARTING TO W 1021 FORES  
SMELL A BIT MUSTY WHERE WATER HAS GOTTEN  
IN SLIDEOUT \*NOTING\*

Continued on page 2

Work Order : 12386B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
        CAUSE:           tested both slides fully extended with
                           water spraying on them for about half
                           hour per slide i cannot find where
                           customer was sayings water getting in
                           there was a little water in corner
                           blocks but that normal for them to
                           caught water and drain out
        CORRECTION:      pics taken after testing for 1 1/2 of
                           soaking near inside fascia i found
                           exposed wood on exterior wall of slide
                           out will have to go back and reseal
                           with non leveling black dicor cant seal
                           until dry
2      COMPLAINT:      CUSTOMER STATES THERE IS A LEAK UNDER      W      1021      FORES
                           KITCHEN SINK
        CAUSE:           pics taken i gound that the kitchen sink
                           under counter top wasn't silicone well
                           and leaking
        CORRECTION:      used silicone around sink edges the
                           meets counter top to seal
    
```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
5      822046999 WINDOW, 15" X 24" STATIONAR W-1021      1      41.83   41.83
5      822090387 40" X 12" STATIONARY WINDOW W-1021      1      0.00    0.00
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
4 DIAG DIAGNOSTICS JS W-1021 0.36 140.00 50.40
5 DIAG DIAGNOSTICS JS W-1021 1.00 140.00 140.00
4 WARR MANUFACTURER WARRANTY JS W-1021 1.64 140.00 229.60
1 WARR MANUFACTURER WARRANTY JS W-1021 0.50 140.00 70.00
2 WARR MANUFACTURER WARRANTY JS W-1021 0.50 140.00 70.00
5 DIAG DIAGNOSTICS JS W-1021 1.00 140.00 140.00
    
```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
5 FRT FREIGHT W-1021 0.00 0.00 0.00
    
```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 41.83 700.00 0.00 0.00 0.00 741.83
    
```

Continued on page 3

Work Order : 12386B

\*\*\*\*\*

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	41.83	700.00	0.00	0.00	0.00	741.83

&k2S  
&k0S