

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12386B

Date In: 20 AUG 25 Author: DLUCAS
Promised Date: 31 DEC 25 Stock No: 11408
: Year: 2026
Customer Name: 12979 - BURANT, MARIA Manufacturer: FOREST RIVER
Address: 1546 ARBOR CREEK DRIVE Brand: PUMA DESTINATION
: OAK CREEK, WI Model: 403LFT
Postal/Zip: 53154 Miles/Hrs: 0
Phone#(res): 414-507-8219 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: RMBURANT@GMAIL.COM Tag#: DB: 8/25
Purchased Date: 11 JUN 25 :
Delivery Date: 15 JUL 25 :
InService Date: :
Serial#: 4X4TPUS22TP106390 :

Job # Description JOB INFORMATION Type Bill To

4 COMPLAINT: LEAK ON SLIDEOUT BY PATIO DOOR RIGHT W 1021 FORES
SIDE OF SLIDE BY PATIO DOOR
CAUSE: will need to try sealing the plastic
inside corner with silicone also i think
carpet on the wrong side of fascia board
heavey down pours it get saturated may
have to pull inside fascia wood off to
reattach i think rubber cut to short on
back side of fascia pics taken
CORRECTION: so i used black non leveling laps
sealant to seal all seams on corners box
of them two spots thatvwas leaking i
also removed the decorative fascia from
slide and fast the carpet fot slide
floor behind decorative wood so no water
touches on both slides
5 COMPLAINT: CUSTOMER STATES TWO UPPER WINDOWS MARKED W 1021 FORES
WITH TAPE ARE TAKING WATER ON
CAUSE: on off door side both windows above
slide outs are leaking around the glass
CORRECTION: remove the damage windows used butyl
tape on framework of both windows and
secured to camper i also used silicone
around exterior framework the windows
are sealed
1 COMPLAINT: CUSTOMER STATES CARPET IS STARTING TO W 1021 FORES
SMELL A BIT MUSTY WHERE WATER HAS GOTTEN
IN SLIDEOUT *NOTING*

Continued on page 2

Work Order : 12386B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
        CAUSE:           tested both slides fully extended with
                           water spraying on them for about half
                           hour per slide i cannot find where
                           customer was sayings water getting in
                           there was a little water in corner
                           blocks but that normal for them to
                           caught water and drain out
        CORRECTION:      pics taken after testing for 1 1/2 of
                           soaking near inside fascia i found
                           exposed wood on exterior wall of slide
                           out will have to go back and reseal
                           with non leveling black dicor cant seal
                           until dry
2  COMPLAINT:           CUSTOMER STATES THERE IS A LEAK UNDER    W    1021    FORES
                           KITCHEN SINK
        CAUSE:           pics taken i gound that the kitchen sink
                           under counter top wasn't silicone well
                           and leaking
        CORRECTION:      used silicone around sink edges the
                           meets counter top to seal
    
```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
5     822046999 WINDOW, 15" X 24" STATIONAR W-1021     2     41.83   83.66
5     822090387 40" X 12" STATIONARY WINDOW W-1021     1      0.00    0.00
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to   Hrs   Rate   Total
*****
4  DIAG          DIAGNOSTICS           JS    W-1021   0.36  140.00  50.40
5  DIAG          DIAGNOSTICS           JS    W-1021   1.00  140.00  140.00
4  WARR          MANUFACTURER WARRANTY JS    W-1021   1.64  140.00  229.60
1  WARR          MANUFACTURER WARRANTY JS    W-1021   0.50  140.00   70.00
2  WARR          MANUFACTURER WARRANTY JS    W-1021   0.50  140.00   70.00
5  DIAG          DIAGNOSTICS           JS    W-1021   1.00  140.00  140.00
    
```

```

*****
Job # Excode   Description EXTRAS           bill to   Qty   Price   Total
*****
5  FRT          FREIGHT                W-1021   0.00   0.00    0.00
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id           Parts   Labour   Sublet   Extras   Tax   Total
*****
W    1021                83.66   700.00   0.00    0.00    0.00  783.66
    
```

Continued on page 3

Work Order : 12386B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	83.66	700.00	0.00	0.00	0.00	783.66

&k2S
&k0S