

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12409B

Date In:	06 AUG 25	Author:	DLUCAS
Promised Date:	25 DEC 25	Stock No:	11257
:	:	Year:	2025
Customer Name:	97468 - BEILKE, CRAIG	Manufacturer:	FOREST RIVER
Address:	4710 MESKER ST	Brand:	PUMA DESTINATION
:	SCHOFIELD, WI	Model:	401RLFT
Postal/Zip:	54476	Miles/Hrs:	0
Phone#(res):	715-297-0027	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	CBASS1021@HOTMAIL.COM	Tag#:	DB: 8/11
Purchased Date:	10 JUL 25	:	:
Delivery Date:	14 AUG 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS25SP104082	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 01- the propane        W    1021    FORES
        hold down is bent
        CAUSE:      Took hold down off of a crossroads
                   hampton vin#330033
        CORRECTION: Done REQUEST .30 HOUR LABOR  WARR AUTH:
                   .30
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 02- one of the        W    1021    FORES
        propane tank Handle got bent in and is
        into the tank
        CAUSE:      Both tanks had a dent so I replaced both
                   I took both new tanks from a crossroads
                   Hampton vin#330033
        CORRECTION: Done REQUEST .30 HOURS OF LABOR  WARR
                   AUTH: .20
ISR0    COMPLAINT:  INTERNAL STOCK REPAIR 03- needs new        W    1021    FORES
        propane regulator
        CAUSE:      Replaced regulator
        CORRECTION: Done REQUEST .85 HOURS OF LABOR  WARR
                   AUTH: .50
WARR    COMPLAINT:  WARRANTY REPAIR 1 - screen door is bent. W    1021    FORES
        CAUSE:      install new screen door  Patio door
                   bent, order new 30 inches wide by 71 1/2
                   inches tall
        CORRECTION: the screen door is onand adjustments
                   made .
WARR    COMPLAINT:  WARRANTY REPAIR 2 - cabinet door in loft W    1021    FORES
        above the bathroom has a crack in it
        CAUSE:      Cabinet door in loft above bathroom
```

Continued on page 2

Work Order : 12409B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                closest to the stairs has a crack in it,
                                needs new 24in tall by 14in wide door.
WARR    CORRECTION: complete
COMPLAINT: WARRANTY REPAIR 3 -cabinet door above tv W      1021    FORES
                                on the right has a crack in it
CAUSE:   Cabinet above the tv on the right has a
                                crack in it, order a 10inch wide and 21
                                inches long door
CORRECTION: complete
WARR    COMPLAINT: WARRANTY REPAIR 4 - several cabinet      W      1021    FORES
                                doors have cracks in them
CAUSE:   Several cabinet doors had cracks in
                                them, I covered them with putty all very
                                small
CORRECTION: Done. REQUEST .70 HOURS OF LABOR  WARR
AUTH: .70 HOURS
WARR    COMPLAINT: WARRANTY REPAIR 5 - piece of trim above  W      1021    FORES
                                the bathroom door to the left of the
                                loft stairs is coming off.
CAUSE:   Trim above the bathroom door was coming
                                off at the end closest the loft stairs,
                                I nailed it down
CORRECTION: Done. REQUEST .20 WARR AUTH: .10

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
ISR01 815505012447 HOLD-DOWN BAR HEAVY DUTY W-1021      1        7.36        7.36
ISR01 756815624626 LP THREADED ROD 1/2 " 24 W-1021      1       10.92       10.92
ISR03 815505013253 AUTO CHANGE OVER REG.      W-1021      1       47.74       47.74
WARR0 109672        CATCH DOOR      W-1021      1        0.44        0.44
WARR0 822053515     SCREEN DOOR, 30-1/8" X 7 W-1021      1       53.13       53.13
WARR0 822048763     DOOR, CABINET, CURIO, 21 W-1021      1       21.65       21.65
WARR0 822048721     DOOR, CABINET, FLAT PANE W-1021      1       34.48       34.48
WARR0 822067847     GLASS, 17-7/16 X 6-7/16 W-1021      1        6.44        6.44

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ISR01 Z991      MISC LABOUR CODE (INTE EG W-1021      0.30    140.00     42.00
ISR02 Z991      MISC LABOUR CODE (INTE EG W-1021      0.20    140.00     28.00
ISR03 Z991      MISC LABOUR CODE (INTE EG W-1021      0.00    140.00      0.00
ISR03 Z991      MISC LABOUR CODE (INTE EG W-1021      0.83    140.00    116.20
ARR01 Z992      MISC LABOUR CODE (WARR EG W-1021      0.50    140.00     70.00
ARR02 Z992      MISC LABOUR CODE (WARR EG W-1021      0.50    140.00     70.00
ARR03 Z992      MISC LABOUR CODE (WARR EG W-1021      0.50    140.00     70.00
ARR04 Z992      MISC LABOUR CODE (WARR EG W-1021      0.70    140.00     98.00
ARR05 Z992      MISC LABOUR CODE (WARR EG W-1021      0.17    140.00     23.80
ARR01 WARR      MANUFACTURER WARRANTY JS W-1021      0.20    140.00     28.00

```

Continued on page 3

Work Order : 12409B

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ISR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00     0.00     0.00
ARR01  FRT      FREIGHT                W-1021    1.00    204.34    204.34
ARR04  FRT      FREIGHT                W-1021    1.00     18.81     18.81
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
W      1021        182.16    546.00     0.00    223.15     0.00    951.31

      Totals        182.16    546.00     0.00    223.15     0.00    951.31

```

&k2S

&k0S