

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12409B

Date In: 06 AUG 25 Author: MGRAY  
Promised Date: 25 DEC 25 Stock No: 11257  
: Year: 2025  
Customer Name: 97468 - BEILKE, CRAIG Manufacturer: FOREST RIVER  
Address: 4710 MESKER ST Brand: PUMA DESTINATION  
: SCHOFIELD, WI Model: 401RLFT  
Postal/Zip: 54476 Miles/Hrs: 0  
Phone#(res): 715-297-0027 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: CBASS1021@HOTMAIL.COM Tag#: DB: 8/11  
Purchased Date: 10 JUL 25 :  
Delivery Date: 14 AUG 25 :  
InService Date: :  
Serial#: 4X4TPUS25SP104082 :

\*\*\*\*\*

Job #	Description	JOB INFORMATION	Type	Bill To
ISRO	COMPLAINT: INTERNAL STOCK REPAIR 01- the propane hold down is bent		W	1021 FORES
	CAUSE: Took hold down off of a crossroads hampton vin#330033			
	CORRECTION: Done REQUEST .30 HOUR LABOR			
ISRO	COMPLAINT: INTERNAL STOCK REPAIR 02- one of the propane tank Handle got bent in and is into the tank		W	1021 FORES
	CAUSE: Both tanks had a dent so I replaced both I took both new tanks from a crossroads Hampton vin#330033			
	CORRECTION: Done REQUEST .30 HOURS OF LABOR			
ISRO	COMPLAINT: INTERNAL STOCK REPAIR 03- needs new propane regulator		W	1021 FORES
	CAUSE: Replaced regulator			
	CORRECTION: Done REQUEST .85 HOURS OF LABOR			
WARR	COMPLAINT: WARRANTY REPAIR 1 - screen door is bent.		W	1021 FORES
	CAUSE: Patio door bent, order new 30 inches wide by 71 1/2 inches tall			
	CORRECTION: . REQUEST .30 HOURS OF LABOR			
WARR	COMPLAINT: WARRANTY REPAIR 2 - cabinet door in loft above the bathroom has a crack in it		W	1021 FORES
	CAUSE: Cabinet door in loft above bathroom closest to the stairs has a crack in it, needs new 24in tall by 14in wide door.			
	CORRECTION: .. REQUEST .30 HOURS OF LABOR			
WARR	COMPLAINT: WARRANTY REPAIR 3 -cabinet door above tv on the right has a crack in it		W	1021 FORES

Continued on page 2

Work Order : 12409B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    CAUSE:      Cabinet above the tv on the right has a
        crack in it, order a 10inch wide and 21
        inches long door
        CORRECTION: .. REQUEST .30 HOURS OF LABOR
WARR    COMPLAINT: WARRANTY REPAIR 4 - several cabinet      W    1021  FORES
        doors have cracks in them
        CAUSE:      Several cabinet doors had cracks in
        them, I covered them with putty all very
        small
        CORRECTION: Done. REQUEST .70 HOURS OF LABOR
WARR    COMPLAINT: WARRANTY REPAIR 5 - piece of trim above  W    1021  FORES
        the bathroom door to the left of the
        loft stairs is coming off.
        CAUSE:      Trim above the bathroom door was coming
        off at the end closest the loft stairs,
        I nailed it down
        CORRECTION: Done. REQUEST .20
    
```

```

*****
Job # Part No      Description                PARTS    Bill to    Qty    Price    Total
*****
ISR01 815505012447 HOLD-DOWN BAR HEAVY DUTY W-1021    1      7.36     7.36
ISR01 756815624626 LP THREADED ROD 1/2 " 24 W-1021    1     10.92    10.92
ISR03 815505013253 AUTO CHANGE OVER REG.    W-1021    1     47.74    47.74
WARR0 109672        CATCH DOOR                W-1021    1      0.44     0.44
    
```

```

*****
Job# Lab Code Description    LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ISR01 Z991    MISC LABOUR CODE (INTE EG W-1021    0.50    140.00    70.00
ISR02 Z991    MISC LABOUR CODE (INTE EG W-1021    0.50    140.00    70.00
ISR03 Z991    MISC LABOUR CODE (INTE EG W-1021    0.00    140.00     0.00
ISR03 Z991    MISC LABOUR CODE (INTE EG W-1021    0.50    140.00    70.00
ARR01 Z992    MISC LABOUR CODE (WARR EG W-1021    0.50    140.00    70.00
ARR02 Z992    MISC LABOUR CODE (WARR EG W-1021    0.50    140.00    70.00
ARR03 Z992    MISC LABOUR CODE (WARR EG W-1021    0.50    140.00    70.00
ARR04 Z992    MISC LABOUR CODE (WARR EG W-1021    0.50    140.00    70.00
ARR05 Z992    MISC LABOUR CODE (WARR EG W-1021    0.50    140.00    70.00
    
```

```

*****
Job # Excode    Description    EXTRAS    bill to    Qty    Price    Total
*****
ISR01 SSE        SHOP SUPPLIES - EXTERNAL W-1021    1.00    0.00     0.00
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id    Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1021        66.46    560.00    0.00    0.00    0.00    626.46
    
```

Continued on page 3

Work Order : 12409B

\*\*\*\*\*

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	66.46	560.00	0.00	0.00	0.00	626.46

&k2S  
&k0S