

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12462

Date In:	28 JUL 25	Author:	MGRAY
Promised Date:	25 DEC 25	Stock No:	
:		Year:	2024
Customer Name:	3060 - SCHAUB, THOMAS	Manufacturer:	GRAND DESIGN
Address:		Brand:	IMAGINE XLS
:	EAGLE RIVER, WI	Model:	22MLE
Postal/Zip:		Miles/Hrs:	
Phone#(res):	715-479-9220	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:		Tag#:	DB: 8/4
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	573TE2621R3439537	:	

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - BATHROOM SINK IS      W    1020    GRAND
        CAUSE:      LEAKING FROM THE HOT WATER SIDE
        The faucet is leaking from the head. The
        faucet will need replacement.  Faucet
        defective. R&R
        CORRECTION:  ... Replaced bathroom faucet. Tested,
        working well, no leaks.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - DRAWER IN KITCHEN      W    1020    GRAND
        REAR BOTTOM, DRAWER WILL NOT STAY IN
        PLACE.
        CAUSE:      The drawer glide fell apart. I replaced
        it
        CORRECTION:  Done. REQUEST .40 HOURS OF LABOR  WARR
        AUTH: .40
WARR    COMPLAINT:  WARRANTY REPAIR 3 - WHEN NOT CONNECTED    W    1020    GRAND
        TO SHOREPOWER, SLIDES WILL NOT WORK.
        CAUSE:      NPF.  I turned the battery disconnect
        off, ran the slide in and out and
        everything is working. I checked the
        voltage at the battery before and after
        being plugged in and the voltage is
        good.
        CORRECTION:  Done.
WARR    COMPLAINT:  WARRANTY REPAIR 4 - refer doors are not    W    1020    GRAND
        remaining open.when storing the unit and
        leaving the doors open to prevent mold
        freezer door is not latching in that.
        CAUSE:      The freezer door latch won't hook into
```

Continued on page 2

Work Order : 12462

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
the plastic block that keeps the doors
open when the unit is stored. The fridge
door will latch to the block. I tried
flipping the block around and it didn't
change anything. We have to see if the
manufacturer wants us to try a different
block, door latch or leave it because
it's still preventing the doors from
closing.
CORRECTION: Replaced door latch bracket, door stays
latched better now.  NEED MANUFACTURER
ADVISEMENT  WARR: .50
WARR COMPLAINT: WARRANTY REPAIR 5 - MATTRESS HAS A DIP IN W      1020    GRAND
CAUSE:          THE MIDDLE OF IT. SIDES ARE NORMAL.
CORRECTION:     Faulty mattress.  We have to see what
                the manufacturer wants to do
                ...INSTALLED MATTRESS REPLACEMENT.
                REQUEST .30 HOURS OF LABOR  WARR AUTH:
                .20
CEU COMPLAINT:   CLEAN EXTERIOR- USED                        E      3060    SCHAU
CAUSE:          1001 CUSTOMER REQUESTED. I washed the
                exterior including the awning and slide
                out.
CORRECTION:     Done.

```

```

*****
Job # Part No  Description      PARTS      Bill to  Qty  Price  Total
*****
WARR0 822057300 BEARING DRAWER GLD 18``  W-1020    2    7.06   14.12
WARR0 82201952  MATTRESS 60 X 80 QUEEN EVER W-1020    1   201.25  201.25
WARR0 82200500  FAUCET LAV PLASTIC J SPOUT  W-1020    1    27.05   27.05
WARR0 822020979 REFRIGERATOR DOOR CATCH ONL W-1020    1     3.77    3.77

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.50  140.00   70.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.50  140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.50  140.00   70.00
ARR04 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.50  140.00   70.00
ARR05 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.50  140.00   70.00
CEU CE          CLEAN EXTERIOR      JGK  E-3060    0.87  140.00  121.80
ARR01 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.00  140.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.00  140.00    0.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.00  140.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.00  140.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR JGK  W-1020    0.00  140.00    0.00
CEU CE          CLEAN EXTERIOR      JGK  E-3060    0.00  140.00    0.00
CEU CE          CLEAN EXTERIOR      JGK  E-3060    0.12  140.00   16.80

```

Continued on page 3

Work Order : 12462

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
CEU CE          CLEAN EXTERIOR      JGK  E-3060    0.11   140.00   15.40
ARR01 W150      FAUCET, R & R      RW   W-1020    0.50   140.00   70.00
ARR04 Z991      MISC LABOUR CODE (INTE RW   W-1020    0.22   140.00   30.80
ARR04 Z991      MISC LABOUR CODE (INTE RW   W-1020    0.28   140.00   39.20

```

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR04  SSE      SHOP SUPPLIES - EXTERNAL  W-1020    1.00    11.55    11.55
ARR01  FRT      FREIGHT FOR FAUCET AND REF W-1020    1.00    18.39    18.39
ARR04  FRT      FREIGHT      W-1020    1.00     0.00     0.00
ARR05  FRT      FREIGHT      W-1020    1.00   168.72   168.72

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
E    3060          0.00    154.00     0.00     0.00     8.48    162.48
W    1020         246.19    490.00     0.00    198.66     0.00    934.85

      Totals      246.19    644.00     0.00    198.66     8.48    1,097.33

```

&k2S
&k0S