

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12542B

Date In:	12 SEP 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11503
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	IMAGINE
:	WISCONSIN RAPIDS, WI	Model:	3100RD
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 9/19
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TE3621T6655755	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - The quarter round that runs along the ceiling edge is coming off in spots.	W	1020 GRAND
	CAUSE:	The ceiling panels have a slight bend to them by the lights causing a gap. I popped the quarter round off, removed the nails, pushed it tight against the ceiling, nailed it back on, and puttied the holes.		
	CORRECTION:	Done. REQUEST 1 HOUR OF LABOR		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - There is an exposed screw hole in the cabinet door to the left of the tv from the manufacturer not mounting it properly.	W	1020 GRAND
	CAUSE:	The manufacturer drilled a hole for the hinge in the wrong spot. Teimmed and puttied the hole		
	CORRECTION:	Done. REQUEST .10 HOURS OF LABOR		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - There is a knick and a scratch in the center cabinrt door above the TV.	W	1020 GRAND
	CAUSE:	Scratches in the caninet door. I covered them with putty		
	CORRECTION:	Done. REQUEST .20 HOURS OF LABOR		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - The style in the cabinet to the right of the tv is ripped.	W	1020 GRAND
	CAUSE:	The style is ripped. I covered it in		

Continued on page 2

Work Order : 12542B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
putty
WARR    CORRECTION: Done.  REQUEST .20 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 5 - There are knicks and W      1020    GRAND
scratches in the cabinetry by the
kitchen sink.
CAUSE:    The cabinet doors are scratched. I
touched all the marks up with putty.
WARR    CORRECTION: Done.  REQUEST .40 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 6 - Two of the magnetic W      1020    GRAND
catches are tweaked in the bathroom.
CAUSE:    I flipped the catch, put the screw in a
different spot and the tab still pulls
away. It's just the design of this
magnet catch.
WARR    CORRECTION: Done.  REQUEST .10 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 7 - There is putty W      1020    GRAND
residue all over the side of the
bathroom cabinet.
CAUSE:    The manufacturer never wiped down the
cabinet after applying putty. I wiped it
off with solvent and a rag.
WARR    CORRECTION: Done.  REQUEUST .20 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 8 - There are scratches W      1020    GRAND
and knicks in the bedroom cabinetry.
CAUSE:    Scratches in the bathroom cabinets. I
touched them up with putty.
WARR    CORRECTION: Done.  REQUEST .30 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 9 - There is a stain on W      1020    GRAND
the wall behind the bathroom door.
CAUSE:    There is a stain on the wall. I cleaned
it off with quick solve and a rag.
WARR    CORRECTION: Done.  REQUEST .30 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 10 - There is white W      1020    GRAND
residue on the awning fabric.
CAUSE:    There is white residue on both sides of
the awning fabric. I cleaned it off with
quick solve and a rag.
WARR    CORRECTION: Done.  REQUEST .80 HOURS OF LABOR
COMPLAINT: WARRANTY REPAIR 11 - The sub-floor W      1020    GRAND
material is ripped and bunched up
underneath the DS cargo door.
CAUSE:    The sub-floor wrap wasnt properly
secured and it pulled out and the floor
is exposed. I cut off all the loose
material, covered it in underbelly tape
and used expanding foam along the edge.
CORRECTION: Done.  REQUEST .75 HOURS OF LABOR

```

Continued on page 3

Work Order : 12542B

```
*****
Job # Part No   Description      PARTS      Bill to   Qty      Price      Total
*****
WARR1 822010030 UNDERBELLY FLOOR GUARD RV B W-1020      9        1.03        9.27
*****
```

```
*****
Job#  Lab Code  Description      LABOUR    Mech Bill to   Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     140.00     70.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.30     140.00     42.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.06     140.00      8.40
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.14     140.00     19.60
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.49     140.00     68.60
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.01     140.00      1.40
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.46     140.00     64.40
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.04     140.00      5.60
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.41     140.00     57.40
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.09     140.00     12.60
ARR05 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     140.00     70.00
ARR05 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.48     140.00     67.20
ARR06 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.02     140.00      2.80
ARR07 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     140.00     70.00
ARR07 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR08 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     140.00     70.00
ARR08 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR09 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     140.00     70.00
ARR09 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR10 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     140.00     70.00
ARR10 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR10 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
ARR11 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.50     140.00     70.00
ARR11 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.00     140.00      0.00
*****
```

```
*****
Job #  Excode   Description      EXTRAS      bill to   Qty      Price      Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL W-1020      1.00      0.00      0.00
*****
```

```
*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      9.27      840.00      0.00      0.00      0.00      849.27
*****
Totals      9.27      840.00      0.00      0.00      0.00      849.27
*****
```

Continued on page 4

Work Order : 12542B

&k2S
&k0S