

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12544

Date In:	11 AUG 25	Author:	MGRAY
Promised Date:	25 DEC 25	Stock No:	11389
:	:	Year:	2025
Customer Name:	17732 - PRICE, DANNY	Manufacturer:	GRAND DESIGN
Address:	8201 MORGAN LAKE RD P.	Brand:	REFLECTION FW
:	FENCE, WI	Model:	360FLS
Postal/Zip:	54120	Miles/Hrs:	:
Phone#(res):	:	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	doot19@gmail.com	Tag#:	9/22
Purchased Date:	30 MAY 25	:	:
Delivery Date:	11 JUL 25	:	:
InService Date:	:	:	:
Serial#:	573FR4022S9929980	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - oven lights for      W    1020    GRAND
          about 25sec then quits - hard to light
          in the oven. need diagnosed on why it
          won't stay lit
          CAUSE:      Diag oven. Wont stay lite for very long
          on main burner. The pilot blows out once
          the main burner lights causing it to
          loose the ability to sense flame causing
          the main burner to go out. Need to
          replace complete stove. Pice uploaded.
          install a pilot assembly
          CORRECTION: ... remove stove top oven completely
          from unit remove the stove top and
          backing of oven remove and installed the
          new pilot assembly after install i also
          tested the oven and the oven is working
WARR    COMPLAINT:  WARRANTY REPAIR 2 - loutlets in bedroom, W    1020    GRAND
          one under tv and one under washer and
          dryer are not working. Plugged something
          in and blew the 15amp fuse, replaced
          fuse and reset and outlets still wont
          work. needs diag for repair/replace
          CAUSE:      Test 120 volt outlets in bedroom. Not
          working. Checked the breakers in
          distrobution panel and those are good.
          Going to neeneed additional time to
          figure out where power is getting
          interrupted. Finally found where the
```

Continued on page 2

Work Order : 12544

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                problem was once i pulled the bottom
                                drawer out next to bed. The wire is
                                smashed in between the floor joist and i
                                beam frame. Will have to install a molex
                                connector in the under belly. Then run a
                                new wire from the connector to the out
                                next to the bed. Would need to drop the
                                spare tire and sewer tube in order to
                                get the underbelly down far enough to
                                have room to work in the underbelly. 3
                                hours labor to complete repair.
CORRECTION: Cut off the pinched section of wire then
                                spliced together with romex connector.
                                Put everything back together. Tested
                                good.
4      COMPLAINT: Transferred to GRV*12544B on 18 AUG 25   E    17732  PRICE
                                Estimate amount was 0.00 needs awning
                                replaced. storm came through and damaged
                                awning. insurance.
CAUSE:      Awning estimate. Removed damaged awning.
CORRECTION: ...
1      COMPLAINT: THERE IS A SPRAY ON THE DOOR CMR           I    SEP    POLIC
                                BELIEVES ITS FROM THE MOUSE FREE. CHECK
                                OUT TO GET REMOVED.
CAUSE:      Check ds pass threw storage door for
                                mouse free over spray. Its not mouse
                                free.
CORRECTION: Had to use rubbing compound to remove
                                what the substance was.
WARR    COMPLAINT: WARRANTY REPAIR 5 - on off door side     E    17732  PRICE
                                in-between slide out and ceter island i
                                found a double a battery wedged under
                                slide out and gouge lino the battery
                                came from a clock laying on floor
CORRECTION: NOTING.

```

```

*****
Job # Part No   Description      PARTS      Bill to   Qty    Price    Total
*****
WARR0 822010039 Self-Contained Power Connec W-1020      2      3.63     7.26
4      822091203 AWNING TUBE ONLY LIGHT BAR E-17732      0     278.85     0.00
4      82200727  AWNING 19' BLACK SOLID FABL E-17732      0     369.76     0.00
4      82200732  AWNING HARDWARE 63" BLK TOP E-17732      0     510.06     0.00
WARR0 822020521 RANGE OVEN PILOT FLAME F/ F W-1020      1      51.43    51.43
*****
Job#  Lab Code  Description    LABOUR    Mech Bill to   Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR TD   W-1020    0.00    140.00     0.00

```

Continued on page 3

Work Order : 12544

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR TD    W-1020      0.50    140.00     70.00
ARR01 O210      RANGE AND OVEN (COMPLE JS    W-1020      0.26    140.00     36.40
ARR02 Z992      MISC LABOUR CODE (WARR TD    W-1020      0.00    140.00       0.00
ARR02 Z992      MISC LABOUR CODE (WARR TD    W-1020      0.39    140.00     54.60
ARR02 Z992      MISC LABOUR CODE (WARR TD    W-1020      0.20    140.00     28.00
ARR02 WARR      MANUFACTURER WARRANTY TD    W-1020      0.00    140.00       0.00
ARR02 WARR      MANUFACTURER WARRANTY TD    W-1020      1.70    140.00    238.00
ARR02 WARR      MANUFACTURER WARRANTY TD    W-1020      2.60    140.00    364.00
ARR02 WARR      MANUFACTURER WARRANTY TD    W-1020      0.05    140.00       7.00
ARR02 WARR      MANUFACTURER WARRANTY TD    W-1020      1.78    140.00    249.20
  4 DIAG      DIAGNOSTICS                      TD    E-17732      0.00    130.00       0.00
  4 DIAG      DIAGNOSTICS                      TD    E-17732      0.00    130.00       0.00
  4 RV4A-1    AWNING R&R COMPLETE EL JS    E-17732      0.00    130.00       0.00
  1 Z992      MISC LABOUR CODE (WARR TD    I-SEP       0.01     70.00      0.70
  1 Z992      MISC LABOUR CODE (WARR TD    I-SEP       0.49     70.00     34.30
ARR02 WARR      MANUFACTURER WARRANTY TD    W-1020      0.10    140.00     14.00
ARR01 O210      RANGE AND OVEN (COMPLE JS    W-1020      0.74    140.00    103.60

```

```

*****
Job #  Excode  Description    EXTRAS      bill to      Qty      Price      Total
*****
ARR02 SSE      SHOP SUPPLIES - EXTERNAL W-1020      1.00       0.00       0.00
ARR01 FRT      FREIGHT                      W-1020      1.00     20.37     20.37

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      SEP              0.00      35.00       0.00       0.00       0.00      35.00
W      1020             58.69    1164.80       0.00     20.37       0.00    1,243.86

      Totals             58.69    1199.80       0.00     20.37       0.00    1,278.86

```

&k2S

&k0S