

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12544

Date In: 11 AUG 25 Author: MGRAY
Promised Date: 19 AUG 25 Stock No: 11389
: Year: 2025
Customer Name: 17732 - PRICE, DANNY Manufacturer: GRAND DESIGN
Address: 8201 MORGAN LAKE RD P. Brand: REFLECTION FW
: FENCE, WI Model: 360FLS
Postal/Zip: 54120 Miles/Hrs:
Phone#(res): Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: doot19@gmail.com Tag#: DB: 8/18
Purchased Date: 30 MAY 25 :
Delivery Date: 11 JUL 25 :
InService Date: :
Serial#: 573FR4022S9929980 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - oven lights for W 1020 GRAND
about 25sec then quits - hard to light
in the oven. need diagnosed on why it
won't stay lit
CAUSE: Diag oven. Wont stay lite for very long
on main burner. The pilot blows out once
the main burner lights causing it to
loose the ability to sense flame causing
the main burner to go out. Need to
replace complete stove. Pice uploaded.
REQUESTING 2.0 HR
CORRECTION: REQUEST .20 HOURS OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 2 - loutlets in bedroom, W 1020 GRAND
one under tv and one under washer and
dryer are not working. Plugged something
in and blew the 15amp fuse, replaced
fuse and reset and outlets still wont
work. needs diag for repair/replace
CAUSE: Test 120 volt outlets in bedroom. Not
working. Checked the breakers in
distrobution panel and those are good.
Going to needed additional time to
figure out where power is getting
interrupted. Finally found where the
problem was once I pulled the bottom
drawer out next to bed. The wire is
smashed in between the floor joist and
i-beam frame. Will have to install a

Continued on page 2

Work Order : 12544

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                molex connector in the under belly. Then
                                run a new wire from the connector to the
                                out next to the bed. Would need to drop
                                the spare tire and sewer tube in order
                                to get the underbelly down far enough to
                                have room to work in the underbelly. 3
                                hours labor to complete repair.
CORRECTION:  ... REQUEST .30 HOURS OF LABOR
COMPLAINT:   Transferred to GRV*12544B on 18 AUG 25   E   17732   PRICE
                                Estimate amount was 0.00 needs awning
                                replaced. storm came through and damaged
                                awning. insurance.
CAUSE:       Awning estimate. Removed damaged awning.
CORRECTION:  ...
1 COMPLAINT:  THERE IS A SPRAY ON THE DOOR CMR           I   SEP   POLIC
                                BELIEVES ITS FROM THE MOUSE FREE. CHECK
                                OUT TO GET REMOVED.
CAUSE:       Check ds pass threw storage door for
                                mouse free over spray. Its not mouse
                                free.
CORRECTION:  Had to use rubbing compound to remove
                                what the substance was.

```

```

*****
Job # Part No  Description           PARTS           Bill to  Qty   Price   Total
*****
4      822091203  AWNING TUBE ONLY LIGHT BAR  E-17732        0    278.85   0.00
4      82200727   AWNING 19' BLACK SOLID FABL E-17732        0    369.76   0.00
4      82200732   AWNING HARDWARE 63" BLK TOP E-17732        0    510.06   0.00
WARR0 EST 721360 - RANGE OVEN COMBO 2 W-1020        0     0.00   0.00

```

```

*****
Job# Lab Code  Description           LABOUR  Mech Bill to  Hrs   Rate   Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR TD  W-1020    0.00  140.00   0.00
ARR01 Z992     MISC LABOUR CODE (WARR TD  W-1020    0.50  140.00  70.00
ARR02 Z992     MISC LABOUR CODE (WARR TD  W-1020    0.00  140.00   0.00
ARR02 Z992     MISC LABOUR CODE (WARR TD  W-1020    0.39  140.00  54.60
ARR02 Z992     MISC LABOUR CODE (WARR TD  W-1020    0.11  140.00  15.40
ARR02 WARR    MANUFACTURER WARRANTY TD  W-1020    0.00  140.00   0.00
4 DIAG       DIAGNOSTICS           TD  E-17732    0.00  130.00   0.00
4 DIAG       DIAGNOSTICS           TD  E-17732    0.00  130.00   0.00
1 Z992       MISC LABOUR CODE (WARR TD  I-SEP     0.01   70.00   0.70
ARR02 WARR    MANUFACTURER WARRANTY TD  W-1020    0.50  140.00  70.00
ARR02 WARR    MANUFACTURER WARRANTY TD  W-1020    0.00  140.00   0.00
ARR02 WARR    MANUFACTURER WARRANTY TD  W-1020    0.00  140.00   0.00
1 Z992       MISC LABOUR CODE (WARR TD  I-SEP     0.49   70.00  34.30
4 RV4A-1     AWNING R&R COMPLETE EL  E-17732    0.00  130.00   0.00
ARR01 O210    RANGE AND OVEN (COMPLE  W-1020    0.00  140.00   0.00

```

Continued on page 3

Work Order : 12544

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR02 WARR      MANUFACTURER WARRANTY      W-1020    0.00   140.00    0.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to    Qty    Price    Total
*****
ARR02  SSE      SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I      SEP          0.00    35.00    0.00    0.00    0.00    35.00
W      1020          0.00   210.00    0.00    0.00    0.00   210.00

Totals          0.00   245.00    0.00    0.00    0.00   245.00
*****
```

&k2S
&k0S