



Warranty Claim Form

Date: 11/4/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR4022S9929980
Reflection 360FLS
Retail Purchase Date: 7/8/2025
Work Started: 9/23/2025
Work Completed: 9/23/2025

Claim Status: Paid
Dealer Work Order #: 12544
Unit Offline Date: 5/1/2025

Claim #: 939708
Labor: \$490.00
Parts: \$58.71
Shipping: \$18.46
Total: \$573.10

Notes: jph 8-20-25 Case 6149923 VIN 573FR4022S9929980 LCI will approve up to .50 for labor. This is pre-auth for the R/R of the THERMOCOUPLE 2021124185. **PLEASE HOLD ALL PARTS FOR 30 DAYS PAST CLAIM.** 720103 Case #6149923 regarding 889063

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

DANNY PRICE
8201 MORGAN LAKE RD
FENCE, Wisconsin 54120
United States
2627074383

Operation Line # 1

Flat Rate Code: 720103 Range/Oven - R & R Range/Oven *Fault Code:* Component Failure Assembly

Problem: Oven lights for about 25 seconds then quits, hard to light in the oven.

Hours: .5

Cause: Won't stay lit for very long on main burner. The pilot blows out once the main burner lights causing it to lose the ability to sense flame causing the main burner to go out.

Amount: 70.00

Remedy: Replace complete stove.

Sublet Repairs:
\$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

| <u>Part</u> | <u>Description</u> | <u>Return Tag #</u> | <u>Qty</u> | <u>Units</u> | <u>Amount</u> |
|--|---|---------------------|------------|--------------|---------------|
| 720521 RANGE OVEN PILOT FLAME F/ FSRI22LA-SS (FURRIION C-FSRI22LA-SS-PFLAME) | RANGE OVEN PILOT FLAME F/ FSRI22LA-SS (FURRIION C-FSRI22LA-SS-PFLAME) | | 1 | 1 | 51.43 |

Operation Line # 2

Flat Rate Code: 410002 Wiring Short/Ground - Rewire/Repair *Fault Code:* Damaged/Maintenance

Problem: Outlets in the bedroom, one under the TV and one under washer and drying are not working. *Hours:* 3
Plugged something in and blew the 15 amp fuse, replaced fuse and reset and outlets still won't work.

Cause: Checked the breakers in distribution panel and those are good. Going to need additional time to *Amount:* 420.00
figure out where power is getting interrupted. Finally found where the problem was once I pulled the bottom
drawer out next to bed. The wire is smashed in between the floor joist and i-beam frame.

Remedy: Will have to install a molex connector in the under belly. Then run a new wire from the connector *Sublet Repairs:*
to the outlet next to the bed. Would need to drop the spare tire and sewer tube in order to get the \$0.00
underbelly down far enough to have room to work in the underbelly.

Manufacturer #:

Model #:

Serial #:

| <u>Part</u> | <u>Description</u> | <u>Return</u> <u>Tag #</u> | <u>Qty</u> | <u>Units</u> | <u>Amount</u> |
|---|---|-------------------------------|------------|--------------|---------------|
| 410039 TERMINAL CROSS OVER CONNECTOR MOLEX 190451000 COC-1 2-COND | TERMINAL CROSS OVER CONNECTOR MOLEX 190451000 COC-1 2-COND CROSSOVER CONN | | 2 | 1 | 7.28 |

Operation Line # 3

Flat Rate Code: 950003 Misc. Charges - Handling Fee

Fault Code: No Problem Identified

Problem: Invoice 1467800 - \$5.93

Hours: 0

Cause: Invoice 1467800 - \$5.93

Amount: 0.00

Remedy: Invoice 1467800 - \$5.93

Sublet Repairs: \$5.93

Manufacturer #:

Model #:

Serial #: