

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12553B

Date In:	01 OCT 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11470
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	420LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TPU82XTP106631	:	:

Job # Description JOB INFORMATION Type Bill To *****

WARR COMPLAINT: WARRANTY REPAIR 1 - the shower handle W 1021 FORES
closest to the door doesnt turn on any
water but the farthest one will.
CAUSE: Both water lines to the shower fauset
were kinked. Will need .50 to repair.
CORRECTION: I cut them down past the kinks and
reattached the fittings. Water now flows
through.
WARR COMPLAINT: WARRANTY REPAIR 2 - the step down to the W 1021 FORES
bedroom is loose.
CAUSE: The stair going into the bedroom was
unlevel and would move when you stepped
on it. will need .65 to repair issue.
CORRECTION: I moved the support down and leveled it
WARR COMPLAINT: WARRANTY REPAIR 3 -at the bottom the the W 1021 FORES
stairs to the loft above the bathroom,
the wall paneling was cut short and the
wood is exposed.
CAUSE: The wall paneling on the stairs was cut
short and had wood exposed. will need
.20 for repair.
CORRECTION: i put a peice of baton strip over it
WARR COMPLAINT: WARRANTY REPAIR 4 - the right cabinet W 1021 FORES
door below the bathroom sink is crooked
and isnt able to close
CAUSE: The cabinet door below the bathroom sink
was uneven.will need .40 for repair.
CORRECTION: i leveled it out and had to move the

Continued on page 2

Work Order : 12553B

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT: latch to make it close properly.
        WARRANTY REPAIR 5 - the bottom left of I   SEP   POLIC
        the slide door track is bent
        CAUSE: The bottom the of left metal slide door
        frame is bent, i tried to strighten it
        out but it wouldnt move. will need 2 hr
        to remove and replace frame as well as
        new frame.
        CORRECTION: will need to remove and replace door
        frame.
WARR    COMPLAINT: WARRANTY REPAIR 6 - there is a bubble in W   1021  FORES
        the alpha around the top of the ladder.
        CAUSE: There was a bubble in the alpha in the
        top of the ladder. Will need .20 for
        repair.
        CORRECTION: I filled the hole and covered it with
        Dicor.
*****
```

```
*****
Job # Part No      Description                PARTS    Bill to    Qty    Price    Total
*****
WARR0 019079008459 COUPLER, 1/2IN BARB X 1/ W-1021      2      0.55     1.10
WARR0 742979298162 1/2 X 1/2 FPT SWIVEL ELB W-1021      1      1.91     1.91
WARR0 677917000333 Dicor 501LSW-1 EPDM Self W-1021      1      8.72     8.72
*****
```

```
*****
Job# Lab Code Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.14 140.00 19.60
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.07 140.00 9.80
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.15 140.00 21.00
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.49 140.00 68.60
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.56 140.00 78.40
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021 0.63 140.00 88.20
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021 0.20 140.00 28.00
ARR04 Z992 MISC LABOUR CODE (WARR EG W-1021 0.31 140.00 43.40
ARR05 Z992 MISC LABOUR CODE (WARR EG I-SEP 0.40 70.00 28.00
ARR05 Z992 MISC LABOUR CODE (WARR EG I-SEP 0.10 70.00 7.00
ARR06 Z992 MISC LABOUR CODE (WARR EG W-1021 0.20 140.00 28.00
*****
```

```
*****
Job # Excode Description                EXTRAS    bill to    Qty    Price    Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
*****
```

Continued on page 3

Work Order : 12553B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	SEP	0.00	35.00	0.00	0.00	0.00	35.00
W	1021	11.73	385.00	0.00	0.00	0.00	396.73
	Totals	11.73	420.00	0.00	0.00	0.00	431.73

&k2S
&k0S