

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12553B

| | | | |
|-----------------|---------------------|-----------------|-------------------|
| Date In: | 01 OCT 25 | Author: | MGRAY |
| Promised Date: | 31 MAY 26 | Stock No: | 11470 |
| : | : | Year: | 2026 |
| Customer Name: | 1021 - FOREST RIVER | Manufacturer: | FOREST RIVER |
| Address: | 21815 NETWORK PLACE | Brand: | PUMA DESTINATION |
| : | CHICAGO, IL | Model: | 420LFT |
| Postal/Zip: | 60673-1218 | Miles/Hrs: | 0 |
| Phone#(res): | 219-534-3167 | Exterior Color: | : |
| Phone#(bus): | 219-534-3167 | Unit Type: | TT-TRAVEL TRAILER |
| Cell Phone: | : | License#: | : |
| Email: | NONE | Tag#: | : |
| Purchased Date: | : | : | : |
| Delivery Date: | : | : | : |
| InService Date: | : | : | : |
| Serial#: | 4X4TPU82XTP106631 | : | : |

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - the shower handle W 1021 FORES
closest to the door doesnt turn on any
water but the farthest one will.
CAUSE: Both water lines to the shower fauset
were kinked. Will need .50 to repair.
CORRECTION: I cut them down past the kinks and
reattached the fittings. Water now flows
through.
WARR COMPLAINT: WARRANTY REPAIR 2 - the step down to the W 1021 FORES
bedroom is loose.
CAUSE: The stair going into the bedroom was
unlevel and would move when you stepped
on it. will need .65 to repair issue.
CORRECTION: I moved the support down and leveled it
WARR COMPLAINT: WARRANTY REPAIR 3 -at the bottom the the W 1021 FORES
stairs to the loft above the bathroom,
the wall paneling was cut short and the
wood is exposed.
CAUSE: The wall paneling on the stairs was cut
short and had wood exposed. will need
.20 for repair.
CORRECTION: i put a peice of baton strip over it
WARR COMPLAINT: WARRANTY REPAIR 4 - the right cabinet W 1021 FORES
door below the bathroom sink is crooked
and isnt able to close
CAUSE: The cabinet door below the bathroom sink
was uneven.will need .40 for repair.
CORRECTION: i leveled it out and had to move the

Continued on page 2

Work Order : 12553B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT: latch to make it close properly.
        WARRANTY REPAIR 5 - the bottom left of W 1021 FORES
        the slide door track is bent
        CAUSE: The bottom the of left metal slide door
        frame is bent, i tried to strighten it
        out but it wouldnt move. will need 2 hr
        to remove and replace frame as well as
        new frame.
        CORRECTION: will need to remove and replace door
        frame.
WARR    COMPLAINT: WARRANTY REPAIR 6 - there is a bubble in W 1021 FORES
        the alpha around the top of the ladder.
        CAUSE: There was a bubble in the alpha in the
        top of the ladder. Will need .20 for
        repair.
        CORRECTION: I filled the hole and covered it with
        Dicor.

```

```

*****
Job # Part No      Description                PARTS    Bill to    Qty    Price    Total
*****
WARR0 019079008459 COUPLER, 1/2IN BARB X 1/ W-1021      2      0.55     1.10
WARR0 742979298162 1/2 X 1/2 FPT SWIVEL ELB W-1021      1      1.91     1.91
WARR0 677917000333 Dicor 501LSW-1 EPDM Self W-1021      1      8.72     8.72

```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.14 140.00 19.60
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.07 140.00 9.80
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.15 140.00 21.00
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.49 140.00 68.60
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.56 140.00 78.40
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021 0.63 140.00 88.20
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021 0.20 140.00 28.00
ARR04 Z992 MISC LABOUR CODE (WARR EG W-1021 0.31 140.00 43.40
ARR05 Z992 MISC LABOUR CODE (WARR EG W-1021 0.40 140.00 56.00
ARR05 Z992 MISC LABOUR CODE (WARR EG W-1021 0.10 140.00 14.00
ARR06 Z992 MISC LABOUR CODE (WARR EG W-1021 0.20 140.00 28.00

```

```

*****
Job # Excode Description                EXTRAS    bill to    Qty    Price    Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00

```

Continued on page 3

Work Order : 12553B

BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax | Total |
|------|---------|-------|--------|--------|--------|------|--------|
| W | 1021 | 11.73 | 455.00 | 0.00 | 0.00 | 0.00 | 466.73 |
| | Totals | 11.73 | 455.00 | 0.00 | 0.00 | 0.00 | 466.73 |

&k2S
&k0S