

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12562

Date In:	15 AUG 25	Author:	MGRAY
Promised Date:	22 AUG 25	Stock No:	11379
:	:	Year:	2025
Customer Name:	9852 - BRONIEC, GREGOR	Manufacturer:	GRAND DESIGN
Address:	1142 W QUEENS WAY	Brand:	REFLECTION 100 SERIES
:	NEKOOSA, WI	Model:	22RK
Postal/Zip:	54457	Miles/Hrs:	:
Phone#(res):	715-459-1101	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 8/19
Purchased Date:	03 APR 25	:	:
Delivery Date:	30 MAY 25	:	:
InService Date:	:	:	:
Serial#:	573FR2820S3353351	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -VINYL IN THE BEDROOM W    1020    GRAND
        ON THE PASSENGER SIDED OF THE BED IS
        LOOSE.
        CAUSE:      Ccheck lino floor in bedroom ds. Lino is
        lifted up from under front over
        hang.need to trim off to resecure lino
        back down. Three hours labor. REQUEST
        3HR
        CORRECTION: ... REQUEST 3 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 2 -SHOWER SURROUND IS      W    1020    GRAND
        MISSING SOME ANCHORS
        CAUSE:      Shower suround moves alot on facet side.
        CORRECTION: Added 4 fasteners to surround. REQUEST
        .20 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - AWNING LOOKS LIKE      W    1020    GRAND
        SOME OF THE FABRIC LINING GOT STUCK AND
        THERES HOLES THROUGH IT NOW.
        CAUSE:      Check awning fabric for defects.
        CORRECTION: Fabric had some salt residue on it
        making look like it had holes in it. Had
        eric wash the fabric. REQUEST .50 HOURS
        OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 4 - DOOR WHERE THE POWER W    1020    GRAND
        CORD PLUGS IN IS LOOSE.
        CAUSE:      Check electrical hatch door for closure.
        Wont stay latched. Would need to replace
        the whole 50 amp inlet..5 labor.
        REQUEST .5 HR
*****
```

Continued on page 2

Work Order : 12562

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: ... REQEUST .50 HOURS OF LABOR
WARR    COMPLAINT:  AC IS VERY RATTLEY. MAKING SOME STRANGE  W    1020    GRAND
          NOISES, WOULD LIKE LOOKED AT FOR
          VERIFICATION IF OK OR NOT.
          CAUSE:      Check ac for operation. Make sure theres
          nothing wrong.
          CORRECTION: Ac tested good for operation. The noises
                     they hear are pretty normal between the
                     compressor noise and the fan noise. The
                     ceiling amplifies the sound alittle bit.
                     REQUEST .20 HOURS OF LABOR

```

```

*****
Job # Part No  Description      PARTS      Bill to  Qty    Price    Total
*****
WARR0 82201894 TUB RIVETS - WHITE 3/4"      W-1020    0      0.25     0.00

```

```

*****
Job#  Lab Code  Description      LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.00   140.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.50   140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.50   140.00   70.00
ARR04 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.00   140.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.50   140.00   70.00
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.11   140.00   15.40
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.02   140.00    2.80
ARR04 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.13   140.00   18.20

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1020          0.00    246.40    0.00     0.00     0.00    246.40

          Totals    0.00    246.40    0.00     0.00     0.00    246.40

```

&k2S
&k0S