

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12562

Date In:	15 AUG 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11379
:	:	Year:	2025
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	REFLECTION 100 SERIES
:	MIDDLEBURY, IN	Model:	22RK
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DROPPING 11/20
Purchased Date:	03 APR 25	:	:
Delivery Date:	30 MAY 25	:	:
InService Date:	:	:	:
Serial#:	573FR2820S3353351	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 -VINYL IN THE BEDROOM W	1020	GRAND
	CAUSE:	ON THE PASSENGER SIDED OF THE BED IS LOOSE. Ckeck lino floor in bedroom ds. Lino is lifted up from under front over hang.need to trim off to resecure lino back down. Three hours labor. REQUEST 3HR		
	CORRECTION:	... REQUEST 3 HOURS OF LABOR WARR AUTH: 2 HOURS OF LABOR		
WARR	COMPLAINT:	WARRANTY REPAIR 2 -SHOWER SURROUND IS MISSING SOME ANCHORS	W	1020 GRAND
	CAUSE:	Shower suround moves alot on facet side.		
	CORRECTION:	Added 4 fasteners to surround. REQUEST .20 HOURS OF LABOR WARR AUTH: .20 HOURS		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - AWNING LOOKS LIKE SOME OF THE FABRIC LINING GOT STUCK AND THERES HOLES THROUGH IT NOW.	W	1020 GRAND
	CAUSE:	Check awning fabric for defects.		
	CORRECTION:	Fabric had some salt residue on it making look like it had holes in it. Had eric wash the fabric. REQUEST .50 HOURS OF LABOR WARR DENIED		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - DOOR WHERE THE POWER W CORD PLUGS IN IS LOOSE.	W	1020 GRAND
	CAUSE:	Check electrical hatch door for closure. Wont stay latched. Would need to replace		

Continued on page 2

Work Order : 12562

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
               the whole 50 amp inlet..5 labor.
CORRECTION: Installed new 50 amp inlet. ... REQEUST
              .50 HOURS OF LABOR WARR AUTH: .40 HOURS
              OF LABOR
WARR    COMPLAINT: AC IS VERY RATTLEY. MAKING SOME STRANGE W    1020    GRAND
              NOISES, WOULD LIKE LOOKED AT FOR
              VERIFICATION IF OK OR NOT.
CAUSE:     Check ac for operation. Make sure theres
              nothing wrong.
CORRECTION: Ac tested good for operation. The noises
              they hear are pretty normal between the
              compressor noise and the fan noise. The
              ceiling amplifies the sound alittle bit.
              REQUEST .20 HOURS OF LABOR WARR DENIED

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty    Price    Total
*****
WARR0 82201894  TUB RIVETS - WHITE 3/4"           W-1020        4      0.25     1.00
WARR0 822020776 RECEPT BLACK 50A INLET TWIS W-1020        1     45.42    45.42

```

```

*****
Job#  Lab Code  Description           LABOUR    Mech Bill to   Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR    W-1020        0.00   140.00     0.00
ARR01 Z992      MISC LABOUR CODE (WARR TD W-1020        0.00   140.00     0.00
ARR01 Z992      MISC LABOUR CODE (WARR TD W-1020        0.00   140.00     0.00
ARR01 Z992      MISC LABOUR CODE (WARR TD W-1020        1.65   140.00    231.00
ARR01 Z992      MISC LABOUR CODE (WARR TD W-1020        0.35   140.00     49.00
ARR02 Z992      MISC LABOUR CODE (WARR TD W-1020        0.20   140.00     28.00
ARR03 Z992      MISC LABOUR CODE (WARR TD W-1020        0.43   140.00     60.20
ARR04 Z992      MISC LABOUR CODE (WARR    W-1020        0.00   140.00     0.00
ARR04 Z992      MISC LABOUR CODE (WARR TD W-1020        0.00   140.00     0.00
ARR04 WARR      MANUFACTURER WARRANTY TD W-1020        0.38   140.00     53.20
ARR04 WARR      MANUFACTURER WARRANTY TD W-1020        0.09   140.00     12.60
ARR05 Z992      MISC LABOUR CODE (WARR TD W-1020        0.50   140.00     70.00

```

```

*****
Job #  Excode   Description           EXTRAS           bill to   Qty    Price    Total
*****
ARR04  FRT      FREIGHT                               W-1020        1.00    19.68    19.68

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020      46.42    504.00    0.00    19.68    0.00    570.10

```

Continued on page 3

Work Order : 12562

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	46.42	504.00	0.00	19.68	0.00	570.10

&k2S
&k0S