



Warranty Claim Form

Date: 9/29/2025

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573TE2221P3434860

Imagine 17MKE

Retail Purchase Date: 5/12/2025

Work Started: 8/26/2025

Work Completed: 8/26/2025

Claim Status: Paid

Dealer Work Order #: 12586

Unit Offline Date: 5/5/2023

Claim #: 929261

Labor: \$56.00

Parts: \$0.00

Shipping: \$0.00

Total: \$56.00

Notes: JPH 9-5-25

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170

mail@greenewayrv.com

Approved Labor Rate: \$140.00

Customer Information

STUART HENDERSHOT
7004 BLONIEN AVENUE
RUDOLPH, Wisconsin 54475
United States
7153212777

Operation Line # 1

Flat Rate Code: 810037 Coax Cable - R&R Connector

Fault Code: Damaged/Maintenance

Problem: *Unsure on correct labor code* TV and radio are not getting reception.

Hours: .2

Cause: Antenna wire to back side of signal booster was broken and separates.

Amount: 28.00

Remedy: Put a new RG6 connector on cable and signal to TV is now working correctly.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 560016 Entry Door - Adjust Door (Main)

Fault Code: Damaged/Maintenance

Problem: Main door is hard to shut and open.

Hours: .2

Cause: States main door is hard to shut and open. Need more information. Are we referring to the hinges or the latch? Hinges are designed to be tight so the wind doesn't blow it open. The latch is working well.

Amount: 28.00

Remedy: Adjusted the striker plate for door latch, door lock is working well without having to push hard. Deadbolt is also working well without having to pull door.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: