



Warranty Claim Form

Date: 2/26/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2725T6656044
Imagine 2300MK
Retail Purchase Date: null
Work Started: 2/19/2026
Work Completed: 2/19/2026

Claim Status: Paid
Dealer Work Order #: 12699C
Unit Offline Date: 8/19/2025

Claim #: 968328
Labor: \$84.00
Parts: \$58.38
Shipping: \$37.81
Total: \$186.81

Notes: *adjusted handling fee to the items approved on invoices mls 2/20 JPH 1-27-26

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 590019 Fender Skirts - Replace

Fault Code: Improper Installation/Build

Problem: Fender skirt is cracked and needs to be replaced.

Hours: .5

Cause: Fender skirt is cracked from manufacturer.

Amount: 70.00

Remedy: Replace fender skirt.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
571000 TRIM ABS TANDEM FENDER SKIRT BLACK 16"/18"	TRIM ABS TANDEM FENDER SKIRT BLACK 16"/18"		1	1	57.40

Operation Line # 2

Flat Rate Code: 560005 Entry Door - R&R Bumper/Holdback/ Catch Fault Code: Component Failure

Problem: The door hold back for the entry door is broken and needs to be replaced.

Hours: .1

Cause: The door hold back is broken and needs to be replace, it broke right at the connection to the unit.

Amount: 14.00

Remedy: Replace door hold back.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
590502 CATCH ENTRY DOOR 90 DEGREE BLACK	CATCH ENTRY DOOR 90 DEGREE BLACK		1	1	0.98

Operation Line # 3

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified
Fee

Problem: Invoice 1537211 - \$0.13 Invoice 1537576 - \$6.62

Hours: 0

Cause: Invoice 1537211 - \$0.13 Invoice 1537576 - \$6.62

Amount: 0.00

Remedy: Invoice 1537211 - \$0.13 Invoice 1537576 - \$6.62

Sublet Repairs: \$6.62

Manufacturer #:

Model #:

Serial #: