

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12710B

Date In:	16 SEP 25	Author:	KOTT
Promised Date:	25 DEC 25	Stock No:	11500
:	:	Year:	2026
Customer Name:	17843 - CAMPBELL, KERR	Manufacturer:	GRAND DESIGN
Address:	1962 19TH CREEK	Brand:	TRANSCEND
:	ARKDALE, WI	Model:	315RKT
Postal/Zip:	54613	Miles/Hrs:	0
Phone#(res):	6085166746	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	KERRI@KERRICAMPBELL.NE	Tag#:	DB: 9/19
Purchased Date:	09 SEP 25	:	:
Delivery Date:	18 SEP 25	:	:
InService Date:	:	:	:
Serial#:	573TT3721T8840719	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
3       COMPLAINT:  FIX TABLE (WOBBLY)                                W    1020    GRAND
      CAUSE:      Loose knobs
      CORRECTION: Tightened the knobs and tightened the
                  cinch clamp  REQUEST .10 HOURS OF LABOR

WARR    COMPLAINT:  WARRANTY REPAIR 1 - shower base is not          W    1020    GRAND
                  sealed properly it allows water to seep
                  out of the side of the shower base
      CAUSE:      Improper sealing of shower base from mfg
      CORRECTION: Used air nozzle to get all water away
                  from where I need to seal then used
                  clear sealant to seal the base no longer
                  allowing water to get through  REQUEST
                  .50 HOURS OF LABOR

WARR    COMPLAINT:  WARRANTY REPAIR 2 - bathroom door is            W    1020    GRAND
                  touching at the top but see through the
                  bottom
      CAUSE:      Mfg installed incorrectly
      CORRECTION: Removed the header and adjusted the
                  rollers it now is touching at top and
                  bottom the same also when reinstalling
                  header put screw in straight so door
                  does not rub on header  REQUEST .20
                  HOURS OF LABOR

WARR    COMPLAINT:  WARRANTY REPAIR 3 -edge of bedroom door        W    1020    GRAND
                  is scraped
      CAUSE:      Mfg- SCRATCHED
      CORRECTION: Used wood crayon to cover  REQUEST .10
```

Continued on page 2

Work Order : 12710B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  HOURS OF LABOR
          WARRANTY REPAIR 4 - top edge of drawer  W    1020    GRAND
          in the bedroom is scraped
          CAUSE:      Scrape
          CORRECTION: Used putty to cover the scrape  REQUEST
                      .30 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - scratches and          W    1020    GRAND
          scrapes throughout the unit
          CAUSE:      Scrapes chips in wood from mfg
          CORRECTION: Used putty and wood crayon to fill or
                      cover scrapes ,chips holes  REQUEST .30
                      HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 6 - roof has 3 bubbles    W    1020    GRAND
          that need to be sealed
          CAUSE:      Bubbles in dicor
          CORRECTION: Cleaned areas then filled with dicor and
                      covered with dicor  REQUEST .30 HOURS OF
                      LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 7 - the shower surround  W    1020    GRAND
          has 2 cracks in the walls
          CAUSE:      The mfg used a cracked surround and
                      tried to cover them with glue or sealant
                      . Please order new shower surround pics
                      taken of tag and cracks
          CORRECTION: .....  REQUEST 3 HOURS OF LABOR

```

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to    Hrs    Rate    Total
*****
3 WARR    MANUFACTURER WARRANTY  HOD  W-1020    0.50    140.00    70.00
ARR01 Z992  MISC LABOUR CODE (WARR HOD  W-1020    0.50    140.00    70.00
ARR02 Z992  MISC LABOUR CODE (WARR HOD  W-1020    0.20    140.00    28.00
ARR03 Z992  MISC LABOUR CODE (WARR HOD  W-1020    0.10    140.00    14.00
ARR04 Z992  MISC LABOUR CODE (WARR HOD  W-1020    0.30    140.00    42.00
ARR05 Z992  MISC LABOUR CODE (WARR HOD  W-1020    0.50    140.00    70.00
ARR06 Z992  MISC LABOUR CODE (WARR HOD  W-1020    0.30    140.00    42.00
ARR07 Z992  MISC LABOUR CODE (WARR HOD  W-1020    0.50    140.00    70.00

```

```

*****
Job #  Excode    Description    EXTRAS    bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00

```

```

*****
Type Bill Id    Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1020        0.00    406.00    0.00    0.00    0.00    406.00

```

Continued on page 3

Work Order : 12710B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	0.00	406.00	0.00	0.00	0.00	406.00

&k2S
&k0S