

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 12769

Date In: 18 SEP 25 Author: MGRAY
 Promised Date: 31 MAY 26 Stock No: 11468
 : Year: 2026
 Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
 Address: 8220 STATE HWY 13 SOUT Brand: PUMA DESTINATION
 : WISCONSIN RAPIDS, WI Model: 403LFT
 Postal/Zip: 54494 Miles/Hrs: 0
 Phone#(res): 800-758-2272 Exterior Color:
 Phone#(bus): Unit Type: TT-TRAVEL TRAILER
 Cell Phone: License#:
 Email: NONE Tag#: emailed parts inquiry:
 Purchased Date: :
 Delivery Date: :
 InService Date: :
 Serial#: 4X4TPUS27TP106899 :

Job #	Description	JOB INFORMATION	Type	Bill To
CEN	COMPLAINT: CLEAN EXTERIOR- NEW CAUSE: For show CORRECTION: Washed		I	PDI PRE-D
NTTS	COMPLAINT: NEW TRAVEL TRAILER STOCK PREP CAUSE: New stock unit CORRECTION: Prepped unit		I	PDI PRE-D
WS	COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED - TOWABLE CAUSE: Prepped CORRECTION: Winterize after prepped		I	PDI PRE-D
WARR	COMPLAINT: WARRANTY REPAIR 1 -the closet door in the bedroom does not close it gets stuck on the floor CAUSE: Mfg did not install door correctly CORRECTION: Removed hinges and removed both doors installed a small shim under the main floor hold then reinstalled the doors and hinges no longer rubbing or getting stuck on the flooring works as it should REQUEST 1 HOUR OF LABOR WARRANTY AUTH: .07 HOURS OF LABOR		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 2 -cabinet door beneath the kitchen sink the right hand side one is misaligned and it's very hard to open CAUSE: Misaligned latch CORRECTION: Adjusted latch REQUEST REQUEST .10 HOURS OF LABOR WARR AUTH: .10 HOURS		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 3 -the high up Windows		W	1021 FORES

Continued on page 2

Work Order : 12769

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                have silicone smeared on the inside and
                outside of the glass
    CAUSE:      Mfg left smeared silicone all over the
                windows inside and out
    CORRECTION: Used quick solve to remove the sealant
                on alot of windows and globs on the
                units exterior metal  REQUEST .75 HOURS
                OF LABOR  WARRANTY AUTH: .60 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 4 - loose strings going  W    1021  FORES
                up into the loft area on the stairs from
                carpet edges
    CAUSE:      Loose strings from carpet edges and
                staples not set in carpet
    CORRECTION: Burned strings and pulled protruding
                staples  REQUEST .20 HOURS OF LABOR
                WARRANTY AUTH: .20 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 5 - staple holes           W    1021  FORES
                throughout the unit
    CAUSE:      Staple holes
    CORRECTION: Used putty to fill took .10 TO REPAIR
                WARRANTY AUTH: .10 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 6 - upper window above  W    1021  FORES
                table has a scratch in the glass
    CAUSE:      Scratch in glass of window from mfg
                Order new window 41" wide x 12" Tall
                that's the rough cut opening . Pic of
                only emblem on window taken no sticker
                on the window only the emblem R&R window
                above dinette slide.
    CORRECTION: ..... Removed window and installed
                new one. Took more time than usuall
                being up above the slide. No
                identification tags on new window.
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
WS     071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI           3     7.55    22.65
WARR0 822090387     40" X 12" STATIONARY WIN W-1021           1    65.51    65.51
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
CEN CE CLEAN EXTERIOR HOD I-PDI 0.78 70.00 54.60
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 1.51 70.00 105.70
WS W495 WINTERIZE RV (WATER SY HOD I-PDI 0.61 70.00 42.70
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.70 140.00 98.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.09 140.00 12.60
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.48 140.00 67.20
    
```

Continued on page 3

Work Order : 12769

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.19   140.00   26.60
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.10   140.00   14.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00   140.00    0.00
NTTS  RV1F-1A   NEW STOCK PREP          HOD I-PDI    2.16    70.00  151.20
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.01   140.00    1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.01   140.00    1.40
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.01   140.00    1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.10   140.00   14.00
WS    W495      WINTERIZE RV (WATER SY HOD I-PDI    0.09    70.00    6.30
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00   140.00    0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.02   140.00    2.80
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00   140.00    0.00
NTTS  RV1F-1A   NEW STOCK PREP          HOD I-PDI    0.41    70.00   28.70
CEN   CE       CLEAN EXTERIOR          HOD I-PDI    0.00    70.00    0.00
NTTS  RV1F-1A   NEW STOCK PREP          HOD I-PDI    0.42    70.00   29.40
CEN   CE       CLEAN EXTERIOR          HOD I-PDI    0.22    70.00   15.40
ARR06 WARR      MANUFACTURER WARRANTY  TD   W-1021    2.00   140.00  280.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00
ARR06  FRT      FREIGHT      W-1021  0.00  0.00  0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
I    PDI      22.65  434.00  0.00   0.00   0.00  456.65
W    1021     65.51  519.40  0.00   0.00   0.00  584.91

Totals      88.16  953.40  0.00   0.00   0.00  1,041.56
*****
```

&k2S
&k0S