

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12769

Date In: 18 SEP 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11468
: Year: 2026
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: PUMA DESTINATION
: WISCONSIN RAPIDS, WI Model: 403LFT
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4TPUS27TP106899 :

Job #	Description	JOB INFORMATION	Type	Bill To
CEN	COMPLAINT: CLEAN EXTERIOR- NEW CAUSE: For show CORRECTION: Washed		I	PDI PRE-D
NTTS	COMPLAINT: NEW TRAVEL TRAILER STOCK PREP CAUSE: New stock unit CORRECTION: Prepped unit		I	PDI PRE-D
WS	COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED - TOWABLE CAUSE: Prepped CORRECTION: Winterize after prepped		I	PDI PRE-D
WARR	COMPLAINT: WARRANTY REPAIR 1 -the closet door in the bedroom does not close it gets stuck on the floor CAUSE: Mfg did not install door correctly CORRECTION: Removed hinges and removed both doors installed a small shim under the main floor hold then reinstalled the doors and hinges no longer rubbing or getting stuck on the flooring works as it should REQUEST 1 HOUR OF LABOR		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 2 -cabinet door beneath the kitchen sink the right hand side one is misaligned and it's very hard to open CAUSE: Misaligned latch CORRECTION: Adjusted latch REQUEST REQUEST .10 HOURS OF LABOR		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 3 -the high up Windows have silicone smeared on the inside and		W	1021 FORES

Continued on page 2

Work Order : 12769

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                outside of the glass
CAUSE:   Mfg left smeared silicone all over the
                                windows inside and out
CORRECTION: Used quick solve to remove the sealant
                                on alot of windows and globs on the
                                units exterior metal  REQUEST .75 HOURS
                                OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 4 - loose strings going W    1021    FORES
                                up into the loft area on the stairs from
                                carpet edges
CAUSE:   Loose strings from carpet edges and
                                staples not set in carpet
CORRECTION: Burned strings and pulled protruding
                                staples  REQUEST .20 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - staple holes           W    1021    FORES
                                throughout the unit
CAUSE:   Staple holes
CORRECTION: Used putty to fill took .10 TO REPAIR
WARR    COMPLAINT:  WARRANTY REPAIR 6 - upper window above W    1021    FORES
                                table has a scratch in the glass
CAUSE:   Scratch in glass of window from mfg
                                Order new window 41" wide x 12" Tall
                                that's the rough cut opening . Pic of
                                only emblem on window taken no sticker
                                on the window only the emblem
CORRECTION: .....  REQUEST 2 HOURS OF LABOR
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty    Price    Total
*****
WS     071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI           3      7.55    22.65
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
CEN CE CLEAN EXTERIOR HOD I-PDI 0.78 70.00 54.60
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 1.51 70.00 105.70
WS W495 WINTERIZE RV (WATER SY HOD I-PDI 0.61 70.00 42.70
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.49 140.00 68.60
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.49 140.00 68.60
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.23 140.00 32.20
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.49 140.00 68.60
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 140.00 70.00
ARR06 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 140.00 70.00
NTTS RV1F-1A NEW STOCK PREP HOD I-PDI 2.16 70.00 151.20
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.01 140.00 1.40
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.01 140.00 1.40
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.01 140.00 1.40
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.01 140.00 1.40
    
```

Continued on page 3

Work Order : 12769

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
WS W495  WINTERIZE RV (WATER SY HOD I-PDI 0.09 70.00 6.30
ARR03 Z992  MISC LABOUR CODE (WARR HOD W-1021 0.14 140.00 19.60
ARR03 Z992  MISC LABOUR CODE (WARR HOD W-1021 0.02 140.00 2.80
ARR03 Z992  MISC LABOUR CODE (WARR HOD W-1021 0.10 140.00 14.00
NTTS RV1F-1A  NEW STOCK PREP HOD I-PDI 0.41 70.00 28.70
CEN CE  CLEAN EXTERIOR HOD I-PDI 0.00 70.00 0.00
NTTS RV1F-1A  NEW STOCK PREP HOD I-PDI 0.42 70.00 29.40
CEN CE  CLEAN EXTERIOR HOD I-PDI 0.22 70.00 15.40
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01 SSE  SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
I PDI 22.65 434.00 0.00 0.00 0.00 456.65
W 1021 0.00 420.00 0.00 0.00 0.00 420.00
Totals 22.65 854.00 0.00 0.00 0.00 876.65
*****
```

&k2S
&k0S