

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12799

Date In:	23 SEP 25	Author:	MGRAY
Promised Date:	31 MAY 26	Stock No:	11107
:	:	Year:	2024
Customer Name:	17725 - STEINHAUER, AN	Manufacturer:	FOREST RIVER
Address:	3833 COUNTY ROAD A	Brand:	PUMA TT
:	ROSHOLT, WI	Model:	25BHS
Postal/Zip:	54473	Miles/Hrs:	0
Phone#(res):	715-321-4281	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	WS COMP DB:3/6
Purchased Date:	24 MAY 25	:	:
Delivery Date:	05 JUN 25	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUPB6R4020714	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
SS      COMPLAINT: SEASONAL STORAGE                                E    17725  STEIN
      CORRECTION: COMPLETE
WS      COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF          E    17725  STEIN
      CONTAINED - TOWABLE
      CAUSE: Needed to be winterized
      CORRECTION: Been winterized
1       COMPLAINT: THE PLUG IN THE BOTTOM BUNK FOR THE            W    1021  FORES
      PHONE CHARGER HAS A LIGHT ON IT BUT IT
      DOES NOT CHARGE ANYTHING
      CAUSE: pics taken i also checked voltage going
      to usb port is 13.62 but nothing coming
      out Was not charging at usb port
      CORRECTION: will need a new usb charging port ...
      lower bunk area Put in new usb port and
      is charging as shown in picture of my
      phone
2       COMPLAINT: THE WHITE STUFF ON THE BACK OF THE BLIND W    1021  FORES
      ON THE TOP BUNK IS STARTING TO COME OFF
      CAUSE: pics and measurements taken of shade has
      a hole in it Shade was damaged
      CORRECTION: will need a new shade above the bunk
      beds..... Replaced it with new shade
3       COMPLAINT: CUSTOMER STATES THAT THE AWNING ROLLS UP W    1021  FORES
      REALLY WEIRD- IT ALMOST SEEMS LIKE THE
      HARDWARE ON THE LEFT SIDE IF YOU ARE
      LOOKING AT THE SIDE OF THE UNIT DOES NOT
      COME IN ALL THE WAY FLUSH
      CAUSE: pics taken og awning tags what I found
```

Continued on page 2

Work Order : 12799

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                was the awning arm on off motor side was
                                catching at the top
CORRECTION: so i remove the set screw in awning
                                rail and adjustments made to fabric so
                                the arm will retract all the way in
                                after adjustments the awning seems to be
                                closing correctly  REQUESST: .9
*****

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      009114950003 -50 F GLYCERIN FREE BASE E-17725      3          9.34      28.02
1       82207100      RECEPTACLE, BLACK, 12V U W-1021      1          7.89       7.89
2       82205346      SHADE, ROLLER 27 X 17 (2 W-1021      1         40.00     40.00
*****

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
WS W495      WINTERIZE RV (WATER SY JL E-17725      0.40     130.00     52.00
WS W495      WINTERIZE RV (WATER SY JL E-17725      0.30     130.00     39.00
1 WARR      MANUFACTURER WARRANTY JS W-1021      0.50     140.00     70.00
2 WARR      MANUFACTURER WARRANTY JS W-1021      0.50     140.00     70.00
3 WARR      MANUFACTURER WARRANTY JS W-1021      0.50     140.00     70.00
1 WARR      MANUFACTURER WARRANTY JL W-1021      0.50     140.00     70.00
1 WARR      MANUFACTURER WARRANTY      W-1021      0.00     140.00       0.00
2 WARR      MANUFACTURER WARRANTY JL W-1021      0.00     140.00       0.00
2 WARR      MANUFACTURER WARRANTY JL W-1021      0.50     140.00     70.00
*****

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
SS SS      SEASONAL STORAGE      E-17725      1.00     207.00     207.00
SS SSE      SHOP SUPPLIES - EXTERNAL E-17725      1.00        6.83        6.83
SS J-ADJ      QUOTE ADJUSTMENT      E-17725      1.00      -6.83      -6.83
WS J-ADJ      QUOTE ADJUSTMENT      E-17725      1.00     -14.02     -14.02
2 FRT      FREIGHT      W-1021      1.00     42.56     42.56
*****

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      17725      28.02      91.00      0.00      192.98      17.17      329.17
W      1021      47.89      350.00      0.00      42.56      0.00      440.45

Totals      75.91      441.00      0.00      235.54      17.17      769.62
*****

```

&k2S

Continued on page 3

Work Order : 12799

&k0S