

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12807

Date In: 24 SEP 25 Author: MGRAY  
Promised Date: 31 MAY 26 Stock No:  
: Year: 2019  
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER  
Address: 21815 NETWORK PLACE Brand: FLAGSTAFF SHAMR  
: CHICAGO, IL Model: 233S  
Postal/Zip: 60673-1218 Miles/Hrs:  
Phone#(res): 219-534-3167 Exterior Color:  
Phone#(bus): 219-534-3167 Unit Type:  
Cell Phone: License#:  
Email: NONE Tag#:  
Purchased Date: :  
Delivery Date: :  
InService Date: :  
Serial#: 4X4TFLY22KZ160599 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
1 COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF E 120321 FRANK  
CONTAINED - TOWABLE  
CAUSE: winterize  
CORRECTION: all faucets and water lines are  
winterize and the water heater is  
drained and in winterize mode  
2 COMPLAINT: a/c is blowing but air is not cold E 120321 FRANK  
coming out.  
CAUSE: i did amp draw 7.3 amps outside temp is  
62 degrees and air coming out is 41  
degrees delta temp of 41 degrees pics  
taken of model ac for future reference  
CORRECTION: i tested the ac and function as should  
cold air of 41 degrees i did lower the  
freeze sense on evaporate coil so it  
doesn't freeze up  
3 COMPLAINT: water pump does not seem to be working E 120321 FRANK  
well. - IT KEEPS RUNNING BUT HARDLY ANY  
WATER COMES OUT. SEEMS LIKE IT RUNS FOR  
A LONG TIME WHILE NOT PRODUCING  
PRESSURE.  
CAUSE: what i found why water pump was  
shutting off and not having good  
pressure is because the winterizing  
valve was in the wrong position and pull  
air into lines the valve is near water  
pump  
CORRECTION: the pump is working correctly

Continued on page 2

Work Order : 12807

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
4      COMPLAINT:  would like estimate for awning      E    120321 FRANK
        replacement.
        CAUSE:      pic and measurements taken will need new
        awning hardware and fabric the awning
        tubes seems ok it does have awning lighs
        and a light track in gutter so maybe
        replace that as well only because it's
        probably brittle and will break
        CORRECTION: remove the damage hardware and fabric
        from existing awning tube install new
        awning arms also installed new fabric to
        existing tube was ok secured everything
        together anf tested awning in now ok and
        awning lights are working
5      COMPLAINT:  BATHROOM SINK IS ONLY DRIPPLING OUT OF      E    120321 FRANK
        THE FAUCET. UNSURE IF ITS JUST CLOGGED
        SCREEN.
        CAUSE:      what i found was black gunk inside both
        faucets
        CORRECTION: cleaned both sink screens on faucet and
        checked shower head as well all faucets
        getting full water pressure from pump
6      COMPLAINT:  WHERE YOU OPEN THE AWNING THERE IS BLACK E    120321 FRANK
        RUBBER PIECES THAT ARE MISSING BY THE
        PULL STRAP.
        CAUSE:      i recommend replace awning hardware if
        would be pointless to install rubber
        bumpers in bent awning arms
        CORRECTION: needs new awning arms
7      COMPLAINT:  WHERE YOU PLUG IN TO SHORE POWER THE CAP E    120321 FRANK
        HAS BUSTED OFF.
        CAUSE:      needed a new 30 amp shore power
        receptacle
        CORRECTION: remove and installed the new shore power
        connector onto exterior wall i also
        tested after install the shore power is
        working
WARR   COMPLAINT:  TSB - 10-1068 - STAINLESS STEEL SINK      W    1021    FORES
        ATTACHMENT
        CAUSE:      needed sink support brackets pics taken
        CORRECTION: install sink support brackets under sink
        secured with screws on each corner and
        middle the sink is secured

```

```

*****
Job # Part No           Desc   PARTS   Bill to   Qty   Price   Total
*****
WS    071247312003      -50 ANTIFREEZE/ 1  E-12032   0    10.69    0.00
7     822020769          RECEPT 30A 125V MA E-12032   1    81.90    81.90

```

Continued on page 3

Work Order : 12807

```
*****
Job # Part No          Desc      PARTS      Bill to  Qty    Price    Total
*****
4      8952002.400UL      BLACK LED HARDWARE E-12032  1      895.59   895.59
4      AE3108346.017      ROLLER TUBE 17'   E-12032  0      436.04    0.00
WARR0 82202990          SINK PART - TBD: A W-1021  1         0.46    0.46
4      AE3108346.017      ROLLER TUBE 17'   E-12032  0      436.04    0.00
4      DOMR3310524NR.317L R/F17' ONYX FABRIC E-12032  1      839.16   839.16
*****
```

```
*****
Job#  Lab Code  Description      LABOUR  Mech Bill to  Hrs    Rate    Total
*****
WS W495      WINTERIZE RV (WATER SY JS  E-120321  0.70   140.00   98.00
2  DIAG      DIAGNOSTICS              JS  E-120321  0.50   140.00   70.00
3  DIAG      DIAGNOSTICS              JS  E-120321  0.40   140.00   56.00
4  Z990      MISC LABOUR CODE (EXTE JS  E-120321  0.30   140.00   42.00
5  Z990      MISC LABOUR CODE (EXTE JS  E-120321  0.30   140.00   42.00
6  Z990      MISC LABOUR CODE (EXTE JS  E-120321  0.20   140.00   28.00
7  Z990      MISC LABOUR CODE (EXTE JS  E-120321  0.50   140.00   70.00
4  RV4A-1    AWNING R&R COMPLETE EL JS  E-120321  2.32   140.00  324.80
ARR01 Z992      MISC LABOUR CODE (WARR JS  W-1021    0.37   140.00   51.80
ARR01 Z992      MISC LABOUR CODE (WARR JS  W-1021    0.13   140.00   18.20
4  RV4A-1    AWNING R&R COMPLETE EL JS  E-120321  1.26   140.00  176.40
4  RV4A-1    AWNING R&R COMPLETE EL JS  E-120321  0.42   140.00   58.80
*****
```

```
*****
Job #  Excode  Description      EXTRAS      bill to  Qty    Price    Total
*****
WS  SSE      SHOP SUPPLIES - EXTERNAL E-120321  1.00    35.00    35.00
WS  J-ADJ    QUOTE ADJUSTMENT      E-120321  1.00   -28.00   -28.00
ARR01 FRT      FREIGHT              W-1021    1.00   18.87   18.87
4  FRT      FREIGHT FOR JOB 4      E-120321  1.00    9.95    9.95
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E  120321      1816.65     966.00      0.00      16.95     154.02    2,953.62
W  1021         0.46       70.00      0.00      18.87      0.00      89.33

Totals      1817.11    1036.00      0.00      35.82     154.02    3,042.95
*****
```

&k2S  
&k0S