



Warranty Claim Form

Date: 3/5/2026

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573FR3425P9922405

Reflection 303RLS

Retail Purchase Date: null

Work Started: 2/17/2026

Work Completed: 2/25/2026

Claim Status: Paid

Dealer Work Order #: 12905

Unit Offline Date: 8/18/2022

Claim #: 970760

Labor: \$140.00

Parts: \$0.00

Shipping: \$0.00

Total: \$140.00

Notes: Sg 2/18/26 Sealant is part of dealer maintenance and unit has been on the lot for 3.5 yrs. Will cover 1 hr labor

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 590046 Roof Vents - Reseal

Fault Code: Improper Installation/Build

Problem: Water on the floor in the bathroom around the toilet.

Hours: 1

Cause: Pressurized unit with water to see if there are any leaks, none found. Checked on roof around roof vent above the bathroom and found that the sealant on roof vent is cracking open along with several other areas.

Amount: 140.00

Remedy: There are several fixtures on the roof that need to be resealed.

Sublet Repairs:
\$0.00

Manufacturer #:

Model #:

Serial #: