



Warranty Claim Form

Date: 3/11/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2014T3444996
Imagine 15RBA
Retail Purchase Date: null
Work Started: 12/19/2025
Work Completed: 2/27/2026

Claim Status: Paid
Dealer Work Order #: 13035B
Unit Offline Date: 9/24/2025

Claim #: 970854
Labor: \$350.00
Parts: \$227.20
Shipping: \$49.56
Total: \$645.83

Notes: Added GDRV part # and pricing. NN 3.4

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Operation Line # 1

Flat Rate Code: 240006 Regulators - R&R (includes drop *Fault Code:* Component Failure test)

Problem: The LP regulator is not working properly and is allowing too much into the system.

Hours: .9

Cause: The LP regulator was reading 25 inches in the water column, we tried to adjust it but nothing happened. Regulator failure.

Amount: 126.00

Remedy: Replace regulator.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	0.00
240067 REGULATOR KIT W/12" PIGTAILS & BRASS MALE ADAPTER FLAMEKING	REGULATOR KIT W/12" PIGTAILS & BRASS MALE ADAPTER FLAMEKING		1	1	62.01

Operation Line # 2

Flat Rate Code: 660001 Cabinet Doors - R&R Door

Fault Code: Damaged/Maintenance

Problem: Both bed side cabinet mirrors have scratched all over them.

Hours: .6

Cause: Scratches from manufacturer.

Amount: 84.00

Remedy: Replace both cabinet doors/mirrors.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
665348 DOOR CABINET 13 X 42 NATURAL TEAK LC W/MDF E2W MIRROR GLASS	DOOR CABINET 13 X 42 NATURAL TEAK LC W/MDF E2W MIRROR GLASS		1	1	80.22
665348 DOOR CABINET 13 X 42 NATURAL TEAK LC W/MDF E2W MIRROR GLASS	DOOR CABINET 13 X 42 NATURAL TEAK LC W/MDF E2W MIRROR GLASS		1	1	80.22

Operation Line # 3

Flat Rate Code: 510008 Decals - R&R Sidewall Decal/Logo/Die *Fault Code:* Damaged/Maintenance Cut

Problem: The decal below the range hood vent has a scratch in it. *Hours:* 1

Cause: The decal below the range hood vent has a scratch in it a crease where the two pieces of the decal meet. Attempted to repair with paint pen but it is still very noticeable. *Amount:* 140.00

Remedy: Replace decal. *Sublet Repairs:*
\$0.00

Manufacturer #: *Model #:* *Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
512654 DIE CUT IMAGINE SIDE DIE CUT #22-LH	DIE CUT IMAGINE SIDE DIE CUT #22-LH		1	1	4.75

Operation Line # 4

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified Fee

Problem: Invoice 1531306 - \$0.55 Invoice 1533097 - \$9.26 Invoice 1542689 - \$9.26 *Hours:* 0

Cause: Invoice 1531306 - \$0.55 Invoice 1533097 - \$9.26 Invoice 1542689 - \$9.26 *Amount:* 0.00

Remedy: Invoice 1531306 - \$0.55 Invoice 1533097 - \$9.26 Invoice 1542689 - \$9.26 *Sublet Repairs:* \$19.07

Manufacturer #: *Model #:* *Serial #:*