

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13040B

Date In: 12 DEC 25 Author: MGRAY  
Promised Date: 04 JUL 26 Stock No: 11540  
: Year: 2026  
Customer Name: 17879 - FRANTI, PAUL Manufacturer: FOREST RIVER  
Address: N8185 WOODY LN Brand: PUMA CAMPING EDITION  
: IXONIA, WI Model: 20BHCE  
Postal/Zip: 53036 Miles/Hrs: 0  
Phone#(res): Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: MOTO028@YAHOO.COM Tag#: DB: 1/12  
Purchased Date: 07 OCT 25 :  
Delivery Date: 04 JUL 26 :  
InService Date: :  
Serial#: 5ZT2PUJB3T4026728 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 1 - Silicone smeared on W 1021 FORES  
exterior of unit in several areas  
CAUSE: Silicone smears on exterior of unit  
CORRECTION: Used solvent to remove smeared silicone  
REQ: .30  
WARR COMPLAINT: WARRANTY REPAIR 2 - sharp wood shards W 1021 FORES  
beneath the dining bench seats frame  
CAUSE: Mfg left and I'd really rough and  
splintered  
CORRECTION: I used sand paper to remove the sharp  
shards of wood customer could easily  
have gotten some good sized injury's  
from the splinters REQ: .50  
WARR COMPLAINT: WARRANTY REPAIR 3 - Entrance door and W 1021 FORES  
screen door are difficult to close when  
the steps are down  
CAUSE: Door needed to be adjusted especially  
screen door  
CORRECTION: I adjusted screen door then lubed the  
lock catch opened and closed door  
several times works good now easy to  
open and close REQ: .20  
WARR COMPLAINT: WARRANTY REPAIR 4 - Major water leak W 1021 FORES  
from back of the water heater  
CAUSE: The bottom connection on water heater is  
leaking a lot and water has now run  
beneath the wood that mfg sat the water  
heater on top of

Continued on page 2

Work Order : 13040B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: Tried to cleaning connections after
            draining water heater still leaks I then
            removed bottom fitting because it looked
            as though the threads may be shredded a
            bit I replaced it with new connection
            from parts then reconnected the fittings
            filled water heater and so far it is not
            leaking from the back but the rear under
            belly is filled with water and I can
            hear a drip coming from the water heater
            just not the back area where it was
            leaking , I did air pressure test and no
            leaks shown so water had dropped from
            back of water heater and went to belly
            ,I then opened under belly up used a fan
            to dry area out over night then cleaned
            the under belly material and used under
            belly tape to patch the underbelly back
            together REQ: 2.5 HOURS
WARR    COMPLAINT: WARRANTY REPAIR 5 - Bath door is scraped W    1021    FORES
            on edges
            CAUSE:      Scraped
            CORRECTION: Used a wood crayon to cover the scraped
            edge of bathroom door REQ: .10
WARR    COMPLAINT: WARRANTY REPAIR 6 - Mini blind behind    W    1021    FORES
            kitchen sink is not attached on one side
            CAUSE:      The subpar mini blind holders do not
            hold the blind
            CORRECTION: I removed the blind drilled a hole in
            each end used a screw on each side of
            insecure to the well then I reinstalled
            the valance I removed to remove the
            blind REQ: .40
WARR    COMPLAINT: WARRANTY REPAIR 8 - window behind sink    W    1021    FORES
            and window next to dining table are
            unable to be opened
            CAUSE:      Windows are stuck and debris in tracks
            CORRECTION: Blew debris from tracks of window then
            used penetrating oil sprayed tracks well
            then slowly worked windows open then
            closed did this a few times blew out
            more debris now they work as they should
            REQ: .30

```

```

*****
Job# Lab Code Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021    0.50    140.00    70.00
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021    0.00    140.00    0.00

```

Continued on page 3

Work Order : 13040B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00   140.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00   140.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.04   140.00    5.60
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.04   140.00    5.60
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.02   140.00    2.80
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.38   140.00   53.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.01   140.00    1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.01   140.00    1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00   140.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00
ARR04  M        BRASS MALE CONNECTOR     W-1021  1.00  6.50  6.50
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021          0.00    490.00     0.00     6.50     0.00    496.50
      Totals          0.00    490.00     0.00     6.50     0.00    496.50
*****
```

&k2S  
&k0S