



Warranty Claim Form

Date: 11/20/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT2726T8842329

Transcend 22RBX

Retail Purchase Date: null

Work Started: 11/4/2025

Work Completed: 11/4/2025

Claim Status: Paid

Dealer Work Order #: 13043B

Unit Offline Date: 10/1/2025

Claim #: 946390

Labor: \$112.00

Parts: \$0.00

Shipping: \$0.00

Total: \$112.00

Notes: Sg 11/7/25 720016 - Note repaired not replaced *Please hold all parts for a minimum of 30 days after the claim is paid*

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 720016 Range Hood - R&R Fan Blade

Fault Code: Improper Installation/Build

Problem: Stove vent fan is rubbing on the grill.

Hours: .2

Cause: Vent fan blades rubbing on the vent screen.

Amount: 28.00

Remedy: Removed the screw holding screen then bent the blades of the fan upwards. Reinstalled the vent screen, turned it on and it is no longer rubbing.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 660002 Cabinet Doors - Repair Door

Fault Code: Improper Installation/Build

Problem: Mirrored cabinet doors next to the bed on both sides rattle the mirror badly when opening and closing.

Hours: .2

Cause: Manufacturer did not silicone inside of the mirrored edges.

Amount: 28.00

Remedy: Used clear sealant to stop mirror from rattling. *No mirror repair code*

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 680028 Sofa - All - Repair

Fault Code: Improper Installation/Build

Problem: Manufacturer did not plug in the sofa and it is impossible to reach down and just plug it in and the sofa is screwed to the floor.

Hours: .4

Cause: Manufacturer did not plug in sofa all the way so no power seats.

Amount: 56.00

Remedy: We had no choice but to pull up on one end and then unscrew screws holding sofa in place, Sublet go behind plug in sofa then reassemble sofa and screw back down.

Repairs:

\$0.00

Manufacturer #:

Model #:

Serial #: