

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13054

Date In: 25 OCT 25 Author: KOTT
Promised Date: 31 DEC 26 Stock No: 11541
: Year: 2026
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: PUMA CAMPING EDITION
: WISCONSIN RAPIDS, WI Model: 305BHCE
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 1/12
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 5ZT2PUWB8T4026037 :

Job # Description JOB INFORMATION Type Bill To

NTTS COMPLAINT: NEW TRAVEL TRAILER STOCK PREP I PDI PRE-D
CAUSE: Done
CORRECTION: Done
CEN COMPLAINT: CLEAN EXTERIOR- NEW I PDI PRE-D
CAUSE: Washed what I could in time given
CORRECTION: Done
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF I PDI PRE-D
CONTAINED - TOWABLE
CAUSE: New prep
CORRECTION: Done
WARR COMPLAINT: WARRANTY REPAIR 1 - light above main bed W 1021 FORES
works intermittently
CAUSE: Loose wire
CORRECTION: Removed lens dropped light down secured
wire into connector light no longer
flickers REQ .10 WARR AUTH: .10
WARR COMPLAINT: WARRANTY REPAIR 2 - Drawer under kitchen W 1021 FORES
sink does not latch
CAUSE: The catch was not installed far enough
forward to catch good
CORRECTION: Removed the drawer loosened screw on
catch moved forward tightened screws
reinstalled the drawer tested the drawer
now catches as it should REQ: .30 WARR
AUTH: .10
WARR COMPLAINT: WARRANTY REPAIR 3 -Deep staple holes in W 1021 FORES
ceiling trim of slide out
CAUSE: Deep holes inbtrim

Continued on page 2

Work Order : 13054

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: Used putty to cover REQ: .20  WARR AUTH:
.10
WARR    COMPLAINT:  WARRANTY REPAIR 4 -Toilet is leaking at  W    1021  FORES
its base
CAUSE:    Bad seal
CORRECTION:  Removed water line removed toilet
removed seal installed new seal and
tested no leaks  REQ: 1.30  WAWRR AUTH:
.75
WARR    COMPLAINT:  WARRANTY REPAIR 6 -Front decal is          W    1021  FORES
peeling
CAUSE:    Peeling decal the top DS line decal is
peeled up  ORDER NEW FRONT DECAL Decal
on front cap is peeling. Ds stripe.
CORRECTION:  .... Installed new decal.
WARR    COMPLAINT:  WARRANTY REPAIR 7 - baggage lock is not  W    1021  FORES
catching
CAUSE:    Mfg installed it incorrectly would not
latch at all
CORRECTION:  I removed the lip off baggage lock
flipped around and it's too loose so I
bent lip gently out a bit and installed
it how it originally was with the lip
bent out a bit it now locks and unlocks
as it should  REQ: .30  WARR AUTH: .10
WARR    COMPLAINT:  WARRANTY REPAIR 8 -Silicone smeared on  W    1021  FORES
exterior of unit
CAUSE:    Silicone smears
CORRECTION:  Used quick solve to remove the silicone
REQ: .20  WARR AUTH: .20

```

```

*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
WS      009114950003 -50 F GLYCERIN FREE BASE I-PDI          3      6.62     19.86
WARR0  713814072933 HARDWARE, MOUNTING WHITE W-1021      1     32.54     32.54
WARR0  82204150      GRAPHIC; #110 LARGE FR W W-1021      1      8.65      8.65

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
NTTS RV1F-1A  NEW STOCK PREP          HOD  I-PDI          0.62    70.00    43.40
CEN CE      CLEAN EXTERIOR          HOD  I-PDI          0.00    70.00      0.00
WS W495      WINTERIZE RV (WATER SY  HOD  I-PDI          0.70    70.00    49.00
ARR01 Z992    MISC LABOUR CODE (WARR  HOD  W-1021          0.10   140.00    14.00
ARR02 Z992    MISC LABOUR CODE (WARR  HOD  W-1021          0.21   140.00    29.40
ARR03 Z992    MISC LABOUR CODE (WARR  HOD  W-1021          0.10   140.00    14.00
ARR04 Z992    MISC LABOUR CODE (WARR  HOD  W-1021          1.16   140.00   162.40
ARR06 Z992    MISC LABOUR CODE (WARR  HOD  W-1021          0.50   140.00    70.00

```

Continued on page 3

Work Order : 13054

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to      Hrs      Rate      Total
*****
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50     140.00     70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50     140.00     70.00
NTTS RV1F-1A    NEW STOCK PREP      HOD I-PDI      2.76      70.00    193.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.10     140.00     14.00
NTTS RV1F-1A    NEW STOCK PREP      HOD I-PDI      0.28      70.00     19.60
NTTS RV1F-1A    NEW STOCK PREP      HOD I-PDI      0.74      70.00     51.80
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.04     140.00      5.60
CEN CE         CLEAN EXTERIOR      HOD I-PDI      0.10      70.00      7.00
NTTS RV1F-1A    NEW STOCK PREP      HOD I-PDI      0.06      70.00      4.20
NTTS RV1F-1A    NEW STOCK PREP      HOD I-PDI      0.04      70.00      2.80
ARR06 WARR      MANUFACTURER WARRANTY TD W-1021      0.00     140.00      0.00
ARR06 WARR      MANUFACTURER WARRANTY TD W-1021      0.50     140.00     70.00

```

```

*****
Job #  Excode   Description   EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL W-1021      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI         19.86      371.00      0.00      0.00      0.00      390.86
W      1021         41.19      519.40      0.00      0.00      0.00      560.59

Totals          61.05      890.40      0.00      0.00      0.00      951.45

```

&k2S
&k0S