

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13054

Date In:	25 OCT 25	Author:	KOTT
Promised Date:	25 DEC 25	Stock No:	11541
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA CAMPING EDITION
:	WISCONSIN RAPIDS, WI	Model:	305BHCE
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 1/12
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUWB8T4026037	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
NTTS    COMPLAINT:  NEW TRAVEL TRAILER STOCK PREP                I      PDI      PRE-D
        CAUSE:      Done
        CORRECTION: Done
CEN     COMPLAINT:  CLEAN EXTERIOR- NEW                        I      PDI      PRE-D
        CAUSE:      Washed what I could in time given
        CORRECTION: Done
WS      COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF        I      PDI      PRE-D
        CONTAINED - TOWABLE
        CAUSE:      New prep
        CORRECTION: Done
WARR    COMPLAINT:  WARRANTY REPAIR 1 - light above main bed W    1021    FORES
        works intermittently
        CAUSE:      Loose wire
        CORRECTION: Removed lens dropped light down secured
        wire into connector light no longer
        flickers REQ .10
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Drawer under kitchen W    1021    FORES
        sink does not latch
        CAUSE:      The catch was not installed far enough
        forward to catch good
        CORRECTION: Removed the drawer loosened screw on
        catch moved forward tightened screws
        reinstalled the drawer tested the drawer
        now catches as it should REQ: .30
WARR    COMPLAINT:  WARRANTY REPAIR 3 -Deep staple holes in W    1021    FORES
        ceiling trim of slide out
        CAUSE:      Deep holes inbtrim
        CORRECTION: Used putty to cover REQ: .20
*****
```

Continued on page 2

Work Order : 13054

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 4 -Toilet is leaking at  W    1021    FORES
          its base
          CAUSE:      Bad seal
          CORRECTION:  Removed water line removed toilet
                      removed seal installed new seal and
                      tested no leaks    REQ: 1.30
WARR    COMPLAINT:  WARRANTY REPAIR 6 -Front decal is        W    1021    FORES
          peeling
          CAUSE:      Peeling decal the top DS line decal is
                      peeled up  ORDER NEW FRONT DECAL
          CORRECTION:  .....  REQ: .50
WARR    COMPLAINT:  WARRANTY REPAIR 7 - baggage lock is not  W    1021    FORES
          catching
          CAUSE:      Mfg installed it incorrectly would not
                      latch at all
          CORRECTION:  I removed the lip off baggage lock
                      flipped around and it's too loose so I
                      bent lip gently out a bit and installed
                      it how it originally was with the lip
                      bent out a bit it now locks and unlocks
                      as it should  REQ: .30
WARR    COMPLAINT:  WARRANTY REPAIR 8 -Silicone smeared on  W    1021    FORES
          exterior of unit
          CAUSE:      Silicone smears
          CORRECTION:  Used quick solve to remove the silicone
                      REQ: .20

```

```

*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
WS      009114950003 -50 F GLYCERIN FREE BASE I-PDI        3      6.62     19.86
WARR0  713814072933 HARDWARE, MOUNTING WHITE W-1021        1     32.54     32.54

```

```

*****
Job# Lab Code Description    LABOUR    Mech Bill to    Hrs    Rate    Total
*****
NTTS RV1F-1A  NEW STOCK PREP          HOD    I-PDI          0.62    70.00    43.40
CEN CE      CLEAN EXTERIOR          HOD    I-PDI          0.00    70.00     0.00
WS W495     WINTERIZE RV (WATER SY HOD    I-PDI          0.70    70.00    49.00
ARR01 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.50   140.00    70.00
ARR02 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.46   140.00    64.40
ARR03 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.50   140.00    70.00
ARR04 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.40   140.00    56.00
ARR06 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.50   140.00    70.00
ARR07 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.50   140.00    70.00
ARR08 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.50   140.00    70.00
NTTS RV1F-1A  NEW STOCK PREP          HOD    I-PDI          2.76    70.00   193.20
ARR04 Z992  MISC LABOUR CODE (WARR HOD    W-1021        0.10   140.00    14.00
NTTS RV1F-1A  NEW STOCK PREP          HOD    I-PDI          0.28    70.00    19.60

```

Continued on page 3

Work Order : 13054

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
NTTS RV1F-1A    NEW STOCK PREP          HOD  I-PDI        0.74    70.00    51.80
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.04    140.00    5.60
CEN CE         CLEAN EXTERIOR          HOD  I-PDI        0.10    70.00    7.00
NTTS RV1F-1A    NEW STOCK PREP          HOD  I-PDI        0.06    70.00    4.20
NTTS RV1F-1A    NEW STOCK PREP          HOD  I-PDI        0.04    70.00    2.80

```

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I      PDI        19.86    371.00    0.00      0.00      0.00    390.86
W      1021       32.54    490.00    0.00      0.00      0.00    522.54

Totals      52.40    861.00    0.00      0.00      0.00    913.40

```

&k2S
&k0S