

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13068B

Date In:	18 NOV 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11532
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	TRANSCEND
:	WISCONSIN RAPIDS, WI	Model:	245RLT
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT3129T7703719	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -material on sofa and W    1020    GRAND
        recliner fronts have marks /stains on
        thrm
        CAUSE:      Stained fabric
        CORRECTION: Used quick solve to remove stains in
        fabric REQUEST:.2
WARR    COMPLAINT:  WARRANTY REPAIR 2 - bathroom door handle W    1020    GRAND
        towards living area the finish around it
        is gone in one spot
        CAUSE:      Scraped from installing finger pull
        handle on door mfg
        CORRECTION: Used stain pen to cover the missing
        finish REQUEST: .2
WARR    COMPLAINT:  WARRANTY REPAIR 4 -MFG never plugged in W    1020    GRAND
        sofa and no way to access the cord
        behind it to plug it in
        CAUSE:      Mfg did not plug in recliner
        CORRECTION: Pulled recliner up and plugged in the
        cord reinstalled recliner with screws in
        floor that holds it in place REQUEST: .3
WARR    COMPLAINT:  WARRANTY REPAIR 5 - exterior quick W    1020    GRAND
        connection the flap cover fell off when
        I opened it
        CAUSE:      The cover was broken on one end from mfg
        when I opened flap the cover just fell
        off
        CORRECTION: I removed 4 screws then removed complete
        hose connection then removed water line
```

Continued on page 2

Work Order : 13068B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              from back and installed new quick
              connection outlet reinstalled into wall
              and used clear silicone to seal around
              the connection  REQUEST: .3

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 019079613745 SPRAY PORT-BK SA-PORT BL W-1020      1      13.23      13.23
WARR0 822010057      HOSE-15'-COIL BLUE ASSEM W-1020      1      21.11      21.11

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.34      140.00      47.60
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.16      140.00      22.40

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL      W-1020      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      34.34      280.00      0.00      0.00      0.00      314.34
              Totals      34.34      280.00      0.00      0.00      0.00      314.34

```

&k2S
&k0S