

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13085

Date In:	31 OCT 25	Author:	KOTT
Promised Date:	07 NOV 25	Stock No:	11290
:	:	Year:	2025
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	IMAGINE
:	MIDDLEBURY, IN	Model:	2300MK
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	30 JAN 25	:	:
Delivery Date:	04 APR 25	:	:
InService Date:	:	:	:
Serial#:	573TE2722S6653424	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WS      COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF      E      17606  SNYDE
          CAUSE:      NEED WINTERIZE
          CORRECTION:  WINTERIZED
WARR    COMPLAINT:  WARRANTY REPAIR 1 - CUSTOMER STATES THAT W      1020  GRAND
          THE GREY TANK (REAR TANK) THE LEVER
          STICKS AND IS HARD TO PULL AND HARD TO
          PUSH IN- WOULD LIKE TO HAVE LOOKED AT
          CAUSE:      The gate valve rod sticks.  I cleaned
          and lubed it.
          CORRECTION:  Done
4        COMPLAINT:  CUSTOMER MAY WANT TO HAVE THE ADDITIONAL E      17606  SNYDE
          LEVER ADDED TO THE END OF THE BLACK TANK
          DUMP
          CAUSE:      1001 CUSTOMER REQUESTED.  I installed
          the twist on gate valve.
          CORRECTION:  Done.
WARR    COMPLAINT:  WARRANTY REPAIR 3 - CUSTOMER STATES THAT W      1020  GRAND
          ONE OF THE PIECES OF TRIM BY THE BACK
          DOOR HAS COME OFF AND NEEDS TO BE PUT
          BACK UP - LAYING BY THER STOVE.
          CAUSE:      The baton strip fell off.  I stapled it
          back on and covered the holes with
          putty.
          CORRECTION:  Done.
WARR    COMPLAINT:  WARRANTY REPAIR 4 - CUSTOMER STATES THAT W      1020  GRAND
          THE THEATER SEATING HAS USB CHARGING
          PORTS ON THEM AND THEY DO NOT WORK-
```

Continued on page 2

Work Order : 13085

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                NEEDS TO BE LOOKED AT
CAUSE:   It wasnt plugged in. I plugged it back
          in and tested it.
CORRECTION: Done.
7 COMPLAINT: CUSTOMER STATES THAT THEY HAD US INSTALL W      1020    GRAND
          12VOLT PLUGS IN THE UNIT AND THEY ARE
          NOT WORKING- THEY ARE INSTALLED IN THE
          THE PASSTHROUGH AT THE FRONT OF THE UNIT
          AND THERE IS ONE IN THE BEDROOM NEXT TO
          THE BED- IS THERE A FUSE FOR THEM AND
          WHERE WOULD, IT BE.
CAUSE:   Blown glass fuse. We dont have anything
          in this shop to test these 12 volt
          plug-ins so i had to ask around and
          luckily tod had one in his truck. I
          plugged the tester in and it didn't
          light up. I cant remove the 12 volt
          plug-in because there is a collar on the
          backside of the wall that holds it
          tight. I removed the tire link mount
          next to it and pulled the wires through
          and it has an inline glass fuse thats
          blown. We dont have any this small in
          the shop so we will have to find some.
          Its a F10AL250V glass fuse.
CORRECTION: ...
1 COMPLAINT: AWNING ARM AT THE REAR MAY BE BENT.           E      17606  SNYDE
          WOULD LIKE LOOKED AT.
CAUSE:   It looks like the rear awning arm was
          hit by something. The whole arm will
          have to be replaced.
CORRECTION: ...

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      009114950003 -50 F GLYCERIN FREE BASE E-17606      3        9.34      28.02
4       019079000583 TWIST ON VALVE      E-17606      1       30.49      30.49
1       82201068      AWNING HARDWAREW SHORT A E-17606      0       573.93      0.00

```

```

*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
WS W495      WINTERIZE RV (WATER SY JL E-17606      0.70     140.00     98.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.49     140.00     68.60
4 Z990      MISC LABOUR CODE (EXTE JGK E-17606      0.10     130.00     13.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.20     140.00     28.00
ARR04 Z992      MISC LABOUR CODE (WARR JGK W-1020      0.10     140.00     14.00
7 Z990      MISC LABOUR CODE (EXTE JGK W-1020      0.18     140.00     25.20

```

Continued on page 3

Work Order : 13085

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to      Hrs      Rate      Total
*****
   1  Z990      MISC LABOUR CODE (EXTE JGK  E-17606    1.00    130.00    130.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK  W-1020     0.01    140.00     1.40
   7  Z990      MISC LABOUR CODE (EXTE JGK  W-1020     0.82    140.00    114.80
   1  A615      AWNING RAIL, INSTALL          E-17606    0.00    130.00     0.00

```

```

*****
Job #  Excode    Description   EXTRAS      bill to      Qty      Price      Total
*****
  WS   SSE       SHOP SUPPLIES - EXTERNAL  E-17606    1.00     18.08     18.08
  WS   J-ADJ     QUOTE ADJUSTMENT          E-17606    1.00    -45.10    -45.10

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E    17606        58.51      241.00        0.00      -27.02      15.03      287.52
W    1020         0.00      252.00        0.00        0.00        0.00      252.00

      Totals        58.51      493.00        0.00      -27.02      15.03      539.52

```

&k2S
&k0S