

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13102B

Date In:	23 MAR 26	Author:	KOTT
Promised Date:	22 APR 26	Stock No:	11504
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	401RLFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 4/2
Purchased Date:	11 AUG 25	:	:
Delivery Date:	22 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS29TP107505	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Slide outs have exposed wood at bottom of fascia arms this will cause rot also the sidewall of all of the sliderooms is missing metal	W	1021 FORES
	CAUSE:	Mfg built slide out incorrect not running metal on sidewall all of the way down leaving exposed wood		
	CORRECTION:	TOOK PICTURES AS BEST AS POSSIBLE ALL 3 OF THE SLIDES NEED REPAIR SO ASKING 8 HOURS TO REPAIR PREAUTH NEEDED NEED TO SEAL THE BOARDS REQ: 8 HOURS		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - WINDOWS HAVE SILICONE SMEARED ON THEM	W	1021 FORES
	CAUSE:	Mfg smeared silicone on windows		
	CORRECTION:	Used quick solve to remove the clear silicone from windows REQUEST: .5		
WARR	COMPLAINT:	WARRANTY REPAIR 4 -TGE BEDROOMS DS WALL AT BOTTOM IS BULGING OUT	W	1021 FORES
	CAUSE:	Bulging wall from mfg		
	CORRECTION:	Noting , nothing can be done without disassembling wall.		
WARR	COMPLAINT:	WARRANTY REPAIR 5 - DARK WOOD HAS LIGHT COLORED SMEAR MARKS	W	1021 FORES
	CAUSE:	Smears from putty on dark wood		
	CORRECTION:	Used furniture polish to remove the white streaks on the dark wood REQUEST: .3		
WARR	COMPLAINT:	WARRANTY REPAIR 6 -CARPETED STAIRS HAVE	W	1021 FORES

Continued on page 2

Work Order : 13102B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                ALOT OF LOOSE STRINGS
                                CAUSE:      Loose strings from carpet edges
                                CORRECTION:  Used scissors to cut away the strings
                                REQUEST: .2
WARR    COMPLAINT:  WARRANTY REPAIR 7 -THE FLOOR COVERINGS      W      1021    FORES
                                ON SLIDE ROOMS HAVE A FEW AREAS THAT
                                HAVE MISSING COLOR
                                CAUSE:      Color missing on floor coverings in a
                                few spots
                                CORRECTION:  Used a marker to blend in the bare spots
                                REQUEST:.2
WARR    COMPLAINT:  WARRANTY REPAIR 9 - STAPLE STICKING OUT    W      1021    FORES
                                OF TGE CABINET NEXT TO THE STOVE
                                CAUSE:      Protruding staple
                                CORRECTION:  Removed staple      REQUESST?.1
WARR    COMPLAINT:  WARRANTY REPAIR 10 - Water heater door     W      1021    FORES
                                is missing a clip
                                CAUSE:      Missing it's on DAF
                                CORRECTION:  Installed new one   REQUEST: .3

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR1 014717092135 CAM LOCK WATER HEATER ST W-1021      1        6.31      6.31

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.44    140.00    61.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.06    140.00     8.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.49    140.00    68.60
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00    140.00     0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.01    140.00     1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.48    140.00    67.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00    140.00     0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.02    140.00     2.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.27    140.00    37.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00    140.00     0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.22    140.00    30.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.01    140.00     1.40
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50    140.00    70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00    140.00     0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.48    140.00    67.20
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00    140.00     0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.02    140.00     2.80
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.49    140.00    68.60
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.01    140.00     1.40
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.27    140.00    37.80
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.23    140.00    32.20

```

Continued on page 3

Work Order : 13102B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	6.31	560.00	0.00	0.00	0.00	566.31
	Totals	6.31	560.00	0.00	0.00	0.00	566.31

&k2S
&k0S