

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13102B

Date In:	23 MAR 26	Author:	KOTT
Promised Date:	22 APR 26	Stock No:	11504
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	401RLFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DEL@ST: 4/22@9
Purchased Date:	11 AUG 25	:	:
Delivery Date:	22 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS29TP107505	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Slide outs have          W    1021    FORES
          exposed wood at bottom of fascia arms
          this will cause rot also the sidewall of
          all of the sliderooms is missing metal
CAUSE:   Mfg built slide out incorrect not
          running metal on sidewall all of the way
          down leaving exposed wood
CORRECTION:  TOOK PICTURES AS BEST AS POSSIBLE ALL 3
          OF THE SLIDES NEED REPAIR SO ASKING 8
          HOURS TO REPAIR PREAUTH NEEDED  REQ: 8
          HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 3 - WINDOWS HAVE          W    1021    FORES
          SILICONE SMEARED ON THEM
CAUSE:   Mfg smeared silicone on windows
CORRECTION:  Used quick solve to remove the clear
          silicone from windows  REQUEST: .5
WARR    COMPLAINT:  WARRANTY REPAIR 4 -TGE BEDROOMS DS WALL  W    1021    FORES
          AT BOTTOM IS BULGING OUT
CAUSE:   Bulging wall from mfg
CORRECTION:  Noting , nothing can be done without
          disassembling wall.
WARR    COMPLAINT:  WARRANTY REPAIR 5 - DARK WOOD HAS LIGHT  W    1021    FORES
          COLORED SMEAR MARKS
CAUSE:   Smears from putty on dark wood
CORRECTION:  Used furniture polish to remove the
          white streaks on the dark wood  REQUEST:
          .3
WARR    COMPLAINT:  WARRANTY REPAIR 6 -CARPETED STAIRS HAVE  W    1021    FORES
```

Continued on page 2

Work Order : 13102B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                ALOT OF LOOSE STRINGS
                                CAUSE:      Loose strings from carpet edges
                                CORRECTION:  Used scissors to cut away the strings
                                REQUEST:    .2
WARR    COMPLAINT:  WARRANTY REPAIR 7 -THE FLOOR COVERINGS      W      1021    FORES
                                ON SLIDE ROOMS HAVE A FEW AREAS THAT
                                HAVE MISSING COLOR
                                CAUSE:      Color missing on floor coverings in a
                                few spots
                                CORRECTION:  Used a marker to blend in the bare spots
                                REQUEST:    .2
WARR    COMPLAINT:  WARRANTY REPAIR 9 - STAPLE STICKING OUT    W      1021    FORES
                                OF TGE CABINET NEXT TO THE STOVE
                                CAUSE:      Protruding staple
                                CORRECTION:  Removed staple      REQUESST?.1
WARR    COMPLAINT:  WARRANTY REPAIR 10 - Water heater door     W      1021    FORES
                                is missing a clip
                                CAUSE:      Missing it's on DAF
                                CORRECTION:  Installed new one   REQUEST:  .3
*****

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR1 014717092135 CAM LOCK WATER HEATER ST W-1021      1        6.31      6.31
*****

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.44     140.00     61.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.06     140.00      8.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.49     140.00     68.60
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00     140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.01     140.00      1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.48     140.00     67.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00     140.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.02     140.00      2.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.27     140.00     37.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00     140.00      0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.22     140.00     30.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.01     140.00      1.40
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50     140.00     70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00     140.00      0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.48     140.00     67.20
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00     140.00      0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.02     140.00      2.80
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.49     140.00     68.60
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.01     140.00      1.40
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.27     140.00     37.80
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.23     140.00     32.20
*****

```

Continued on page 3

Work Order : 13102B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	6.31	560.00	0.00	0.00	0.00	566.31
	Totals	6.31	560.00	0.00	0.00	0.00	566.31

&k2S
&k0S