

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13102B

Date In:	23 MAR 26	Author:	KOTT
Promised Date:	22 APR 26	Stock No:	11504
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	401RLFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 4/2
Purchased Date:	11 AUG 25	:	:
Delivery Date:	22 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS29TP107505	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Slide outs have exposed wood at bottom of fascia arms this will cause rot also the sidewall of all of the sliderooms is missing metal	W	1021 FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. I removed all the side facia, wrapped the exposed edges in eturnabon tape, removed the nails, nailed everything back on and puttied the holes.		
	CORRECTION:	Done. TOOK PICTURES AS BEST AS POSSIBLE ALL 3 OF THE SLIDES NEED REPAIR SO ASKING 8 HOURS TO REPAIR PREAUTH NEEDED NEED TO SEAL THE BOARDS REQ: 8 HOURS APPROVED: 8HR		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - WINDOWS HAVE SILICONE SMEARED ON THEM	W	1021 FORES
	CAUSE:	Mfg smeared silicone on windows		
	CORRECTION:	Used quick solve to remove the clear silicone from windows REQUEST: .5 APPROVED: .3		
WARR	COMPLAINT:	WARRANTY REPAIR 4 -TGE BEDROOMS DS WALL AT BOTTOM IS BULGING OUT	W	1021 FORES
	CAUSE:	Bulging wall from mfg		
	CORRECTION:	Noting , nothing can be done without disassembling wall.		
WARR	COMPLAINT:	WARRANTY REPAIR 5 - DARK WOOD HAS LIGHT COLORED SMEAR MARKS	W	1021 FORES
	CAUSE:	Smears from putty on dark wood		

Continued on page 2

Work Order : 13102B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: Used furniture polish to remove the
             white streaks on the dark wood  REQUEST:
             .3 APPROVED: .3
WARR    COMPLAINT: WARRANTY REPAIR 6 -CARPETED STAIRS HAVE W    1021    FORES
             ALOT OF LOOSE STRINGS
             CAUSE: Loose strings from carpet edges
             CORRECTION: Used scissors to cut away the strings
             REQUEST: .2 approved: .2
WARR    COMPLAINT: WARRANTY REPAIR 7 -THE FLOOR COVERINGS W    1021    FORES
             ON SLIDE ROOMS HAVE A FEW AREAS THAT
             HAVE MISSING COLOR
             CAUSE: Color missing on floor coverings in a
             few spots
             CORRECTION: Used a marker to blend in the bare spots
             REQUEST:.2 approved: .2
WARR    COMPLAINT: WARRANTY REPAIR 9 - STAPLE STICKING OUT W    1021    FORES
             OF TGE CABINET NEXT TO THE STOVE
             CAUSE: Protruding staple
             CORRECTION: Removed staple REQUESST?.1 apprvoed:.1
WARR    COMPLAINT: WARRANTY REPAIR 10 - Water heater door W    1021    FORES
             is missing a clip
             CAUSE: Missing it's on DAF
             CORRECTION: Installed new one REQUEST: .3 approved:
             .3
WARR    COMPLAINT: WARRANTY REPAIR 11 - The light above the W    1021    FORES
             bed doesn't work.
             CAUSE: The cover wasnt on all the way and the
             button wasnt making good contact. I put
             the cover on correctly and the light
             works.
             CORRECTION: Done. REQUEST: .1

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR1 014717092135 CAM LOCK WATER HEATER ST W-1021      1      6.31      6.31
WARR0 891991000533 ETERNABOND WHITE W-1021      6      1.86      11.16

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to      Hrs      Rate      Total
*****
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021      0.44      140.00      61.60
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021      0.06      140.00      8.40
ARR02 WARR MANUFACTURER WARRANTY JGK W-1021      1.28      140.00      179.20
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021      0.49      140.00      68.60
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021      0.00      140.00      0.00
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021      0.01      140.00      1.40
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1021      0.48      140.00      67.20
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1021      0.00      140.00      0.00

```

Continued on page 3

Work Order : 13102B

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total	

ARR04	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.02	140.00	2.80			
ARR05	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.27	140.00	37.80			
ARR05	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.00	140.00	0.00			
ARR05	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.22	140.00	30.80			
ARR05	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.01	140.00	1.40			
ARR06	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.50	140.00	70.00			
ARR06	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.00	140.00	0.00			
ARR07	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.48	140.00	67.20			
ARR07	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.00	140.00	0.00			
ARR07	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.02	140.00	2.80			
ARR09	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.49	140.00	68.60			
ARR09	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.01	140.00	1.40			
ARR10	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.27	140.00	37.80			
ARR10	Z992	MISC LABOUR CODE (WARR HOD	W-1021	0.23	140.00	32.20			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	0.50	140.00	70.00			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	0.30	140.00	42.00			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	0.88	140.00	123.20			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	1.57	140.00	219.80			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	0.40	140.00	56.00			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	1.24	140.00	173.60			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	0.70	140.00	98.00			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	0.50	140.00	70.00			
ARR02	WARR	MANUFACTURER WARRANTY JGK	W-1021	0.63	140.00	88.20			
ARR11	Z992	MISC LABOUR CODE (WARR JGK	W-1021	0.50	140.00	70.00			

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total

ARR11	SSE	SHOP SUPPLIES - EXTERNAL		W-1021	1.00	0.00	0.00

BILLINGS SUMMARY							
Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

W	1021	17.47	1750.00	0.00	0.00	0.00	1,767.47
Totals		17.47	1750.00	0.00	0.00	0.00	1,767.47

&k2S
&k0S