

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13106

Date In:	04 NOV 25	Author:	MGRAY
Promised Date:	12 NOV 25	Stock No:	11139
:	:	Year:	2024
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	REFLECTION 150 SERIES
:	MIDDLEBURY, IN	Model:	270BN
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	09 APR 25	:	:
Delivery Date:	13 MAY 25	:	:
InService Date:	:	:	:
Serial#:	573FR3129R3349888	:	:

```
*****
Job #   Description                JOB INFORMATION          Type Bill To
*****
WS      WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED -    E    809    ORTH
TOWABLE
WARR    COMPLAINT:  EXTERIOR DOOR IS HARD TO OPEN AND CLOSE. W    1020    GRAND
HAS OILED , BUT DOESN'T SEEM TO HELP.
NEEDS TO SLAM DOOR TO CLOSE FROM OUTSIDE
AND YANK HARD TO SHUT FROM INSIDE.
CAUSE:      the door was warped out
CORRECTION: put the tool that pushes door in
slightly- were able to straighten the
door- now checks okay request .5
WARR    COMPLAINT:  WARRANTY REPAIR 2 - BOTH TAIL LIGHTS      W    1020    GRAND
HAVE CRACKS IN THEM
CAUSE:      Tail lights are cracked
CORRECTION: Replace them with new ones took a little
more time because of how the wires are
run from manufacture request: .8
WARR    COMPLAINT:  WARRANTY REPAIR 3 - BATHROOM SWITCH ONLY W    1020    GRAND
TURNED ON ONCE, NOW DOESN'T WORKS. MAIN
LIGHT WORKS, BUT THE MOTION LIGHT IN THE
BATHROOM DOES NOT WORK.
CAUSE:      Tested switch and light fixture at light
fixture has failed
CORRECTION: Replace it with a new light fixture
request: .4
WARR    COMPLAINT:  WARRANTY REPAIR 4 - THE REFER DOOR LATCH W    1020    GRAND
EITHER WONT LATCH. OR WILL LATCH AND IS
VERY HARD TO OPEN. nEED TO SOMETIMES
LIFT THE BOTTOM OF THE DOOR TO OPEN WHEN
```

Continued on page 2

Work Order : 13106

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                NOT OPENING.
                                CAUSE:      Handle needed to be adjusted on
                                refrigerator
                                CORRECTION: Adjusted handle request: .1
WARR    COMPLAINT:  WARRANTY REPAIR 5 - LEFT RECLINER WHEN      W      1020    GRAND
                                RECLINING, WHEN CLOSING TO GET OUT OF
                                THE CHAIR YOU HAVE TO SLAM BACK HARD TO
                                GET TO CLOSE, FEELS LIKE SOMETHING IS
                                BLOCKING PREVENTING CLOSURE
                                CAUSE:      Recliner arms are bent from manufacture.
                                request replacement for recliner
                                CORRECTION: request: 2.0
1        MATT CHECKING BATTERIERS AND AND SOLAR ITEMS LIKE      E      809    ORTH
WARR    CONVERTER TO VERIFY FUNCTION.
WARR    COMPLAINT:  WARRANTY REPAIR 6 - SLIDE ON THE RIGHT      W      1020    GRAND
                                SIDE WHEN LOOKING AT THE RECLINERS THE
                                WALL NEAR THE EXTERIOR IS BOWING IN.
                                FASCIA BOARD BROKE TRYING TO ADDRESS
                                CAUSE:      SCREWS WERE BROKEN AND PULLED FROM
                                FACSIA, NEEDED REPLACEMENT, WHEN PULLING
                                BOARD FROM WALL TO REPLACE SCREWS,
                                FACISA BOARD BROKE. NEEDS REPLACEMENT.
                                CORRECTION: .. REQUEST: 1.5 HR
2        COMPLAINT:  CMR REQUESTS HAVING LP TOPPED OFF          E      809    ORTH
                                CORRECTION: 30 POUNDS PROPANE

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON E-809          0        9.62        0.00
WARR0 420855        LIGHT REAR 6" OVAL LED 7 W-1020        2        9.62       19.24
WARR0 82200689      MOTION LIGHT 12 V LED SU W-1020        1        6.85        6.85

```

```

*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
WS W495      WINTERIZE RV (WATER SY      E-809          0.00     140.00        0.00
WS W495      WINTERIZE RV (WATER SY EG   E-809          0.00     140.00        0.00
WARR Z992    MISC LABOUR CODE (WARR JL   W-1020         0.40     140.00       56.00
ARR02 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.31     140.00       43.40
ARR02 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.12     140.00       16.80
ARR02 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.07     140.00        9.80
ARR03 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.39     140.00       54.60
ARR03 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.11     140.00       15.40
ARR04 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.50     140.00       70.00
ARR05 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.50     140.00       70.00
ARR06 Z992   MISC LABOUR CODE (WARR      W-1020         0.00     140.00        0.00
ARR06 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.03     140.00        4.20
ARR06 Z992   MISC LABOUR CODE (WARR JL   W-1020         0.41     140.00       57.40

```

Continued on page 3

Work Order : 13106

```
*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
ARR06 Z992      MISC LABOUR CODE (WARR JL   W-1020    0.06    140.00    8.40
*****
```

```
*****
Job #   Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
  WS   SSE      SHOP SUPPLIES - EXTERNAL   E-809     1.00     0.00     0.00
  WS   J-ADJ     QUOTE ADJUSTMENT          E-809     1.00    99.00    99.00
   2   LP        PROPANE                    E-809    30.00     0.74    22.20
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
E    809           0.00     0.00     0.00    121.20     6.68    127.88
W    1020          26.09    406.00     0.00     0.00     0.00    432.09

      Totals       26.09    406.00     0.00    121.20     6.68    559.97
*****
```

&k2S
&k0S