

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13110B

Date In:	20 NOV 25	Author:	MGRAY
Promised Date:	25 DEC 25	Stock No:	11520
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	421LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DEL@ST- TBD
Purchased Date:	08 SEP 25	:	:
Delivery Date:	25 DEC 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPU820TP107724	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
3       COMPLAINT: BACKSPLASH BEHIND STOVE BUBBLING           W    1021    FORES
      CAUSE:         The backsplash above the stove has a
                     bulge it, there is no simple way of
                     taking it off and resticking it, the
                     silicone alone the wall and couter will
                     have to be cut to push the extra
                     material down and the vent hood will
                     have to come off to and glue will have
                     to be put between the wall and the
                     backsplash, will take about 2 hours
      CORRECTION:    .. REQUEST 2.0HR
4       COMPLAINT:  SEAL UP AROUND WHERE PIPING HOLES GOES   W    1021    FORES
      CAUSE:         The holes where the termination hoses
                     come out of the frame from the tank were
                     not sealed from the factory, i sealed
                     them up with expanding foam
      CORRECTION:    Done. REQUESTING .3
WARR   COMPLAINT:  WARRANTY REPAIR 1 - The LP regulator is   W    1021    FORES
      CAUSE:         letting to much propane thru
                     The regulator was holding at 17 inches
                     in the water colum, i replaced the
                     regulator.
      CORRECTION:    Done REQUESTING 1.1HR
WARR   COMPLAINT:  WARRANTY REPAIR 2 - the bathroom light   W    1021    FORES
      CAUSE:         switch causes the fuse to blow, bypassed
                     the wire and found that there is
                     something wrong with the wire they have
```

Continued on page 2

Work Order : 13110B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
run from the panel to the switch, we
will have to run a new wire
CAUSE:  Whenever you turned the rear bathroom
light on it would pop the fuse for the
rear power, somewhere in the wall the
wire is shorted out, i ran a new wire in
the underbelly to the fuse panel and it
is no longer popping fuses.
CORRECTION: Done. REQUESTING 5.5HR
ISR0 COMPLAINT: INTERNAL STOCK REPAIR 01- the front      W      1021  FORES
awning motor cover got melted by the
shop heater and is warped.
CAUSE:  I had the awning out and the shop heater
on and it melted the motor cover on the
front awning arm, i replaced the cover
CORRECTION: Done REQUESTING 1.5HR
WARR COMPLAINT: WARRANTY REPAIR 3 - the left closet door W      1021  FORES
in the rear bedroom has a small crack
around the latch and the latch is not
level so it will not secure.
CAUSE:  Lowered the latch to where it secures
and put putty over the small crack.
CORRECTION: Done REQUESTING .6HR

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 815505013253 AUTO CHANGE OVER REG.      W-1021      1      47.74      47.74
WARR0 815505010665 12" LP HOSE                W-1021      2      22.97      45.94
ISR01 848150059215 REGAL COVER, DRIVE HEAD     W-1021      1      27.42      27.42
ISR01 848150059208 REGAL HEAD, BACK COVER,     W-1021      1      25.75      25.75

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to      Hrs      Rate      Total
*****
3 Z992 MISC LABOUR CODE (WARR EG W-1021      0.50      140.00      70.00
4 Z992 MISC LABOUR CODE (WARR EG W-1021      0.50      140.00      70.00
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021      0.50      140.00      70.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.50      140.00      70.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021      0.00      140.00      0.00
ISR01 Z991 MISC LABOUR CODE (INTE EG W-1021      0.00      140.00      0.00
ISR01 Z991 MISC LABOUR CODE (INTE EG W-1021      0.50      140.00      70.00
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021      0.50      140.00      70.00

```

Continued on page 3

Work Order : 13110B

```
*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00     0.00
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021        146.85    420.00     0.00     0.00     0.00    566.85

      Totals      146.85    420.00     0.00     0.00     0.00    566.85
*****
```

&k2S
&k0S