

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13125B

Date In:	01 DEC 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11542
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	TRANSCEND XPLO
:	WISCONSIN RAPIDS, WI	Model:	23BHX
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 12/1
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT2720T8842844	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -mirrors on cabinet      W    1020    GRAND
        doors next to bed rattle badly while
        opening
        CAUSE:      Mfg did not use silicone to create a
        buffer and allowed mirror to rattle
        badly when opening
        CORRECTION: I used clear silicone and ran a bead
        around backside of the mirror on both
        doors no longer does it rattle after
        siliconing it  REQ: .40
WARR    COMPLAINT:  WARRANTY REPAIR 2 - sofa not plugged in    W    1020    GRAND
        and mfg has screwed down
        CAUSE:      Mfg did not plug in the recliner
        CORRECTION: I had to pull up the sofa and plug the
        cord into ourlet  REQ .30
WARR    COMPLAINT:  WARRANTY REPAIR 3 - privacy curtain has    W    1020    GRAND
        stains
        CAUSE:      Stains on curtain
        CORRECTION: Used fabric cleaner to remember ve the
        stains  REQ .20
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Rear door will not      W    1020    GRAND
        close
        CAUSE:      Improper instsll of latch at mfg
        CORRECTION: Removed latch on doorI had to gently
        pound part of latch close to other metal
        so I could install latch out further I
        drilled new holes and installed the
        latch ,this took a few times for
*****
```

Continued on page 2

Work Order : 13125B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              adjusting so it would lock once steps
              were up and in unit . Now door latches
              and both locks work on rear entrance
              door  REQ .70

```

```

*****
Job # Part No Description      PARTS      Bill to  Qty      Price      Total
*****
WARR0 161128  NOVAFLEX PRO 10 OZ TRANSLUCEN W-1020      1      9.28      9.28

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.29      140.00      40.60
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.01      140.00      1.40
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.20      140.00      28.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.37      140.00      51.80
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.13      140.00      18.20
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00      140.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL      W-1020      1.00      0.00      0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      9.28      280.00      0.00      0.00      0.00      289.28

      Totals      9.28      280.00      0.00      0.00      0.00      289.28

```

&k2S
&k0S