

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13139B

Date In:	05 DEC 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11559
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	TRANSCEND XPLO
:	WISCONSIN RAPIDS, WI	Model:	26BHX
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 12/9
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT3127T8842726	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - the ds LP line from W	1020	GRAND
		regulator the green portion that screws onto bottle is cracked and part has come off		
	CAUSE:	Broken LP line end from mfg this way		
	CORRECTION:	Removed the damaged line installed new line tested no leaks REQ: .40		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - wall panel next to W	1020	GRAND
		shower stall is not finished jagged finish		
	CAUSE:	Unfinished trim next to shower stall		
	CORRECTION:	I used some white silicone to cover the jagged edge of trim after gently sanding the loose finish away REQ: .50		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - Very deep staple W	1020	GRAND
		holes inside some of the cabinets		
	CAUSE:	Deep staple holes in cabinetry		
	CORRECTION:	I used putty to fill all the staple holes in cabinets and the walls of cabinets REQ: .60		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - Both mirrored W	1020	GRAND
		cabinet doors on each side of the bed rattle badly when opening them		
	CAUSE:	No sealant around back of mirrors to prevent them from rattling when opening		
	CORRECTION:	I used clear silicone and ran a bead around the inside edge of the mirrors REQ: .30		

Continued on page 2

Work Order : 13139B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 -Deep scratch on the      W    1020    GRAND
          exterior of bathroom door and on the
          edge of the same door their is a large
          area missing it's finish
          CAUSE:      Scratched door and missing chunk out of
          side of door
          CORRECTION: Used putty to fill the side and filled
          the scratch in   REQ: .50
WARR    COMPLAINT:  WARRANTY REPAIR 6 -All compartment key      W    1020    GRAND
          lock latches do not lock the latches
          need to be flipped around so they make
          it over interior frame of compartment
          doors Only the key type
          CAUSE:      Improper install of key locks on baggage
          doors
          CORRECTION: I removed the screw on 3 locks that hold
          the latch in place then I flipped them
          around reinstalled screw and tested and
          they all lock as they should   REQ: .40
WARR    COMPLAINT:  WARRANTY REPAIR 7 - Linoleum flap near      W    1020    GRAND
          stove on slide room is wrinkled upward
          CAUSE:      Wrinkled up from mfg
          CORRECTION: Used heat gun to get lino  to lay flat
          as possible would like noted in case of
          future issue   REQ: .40

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 815505010696 20" RV TYPE 1 PIGTAIL      W-1020      1      26.53      26.53

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.49      140.00      68.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.01      140.00      1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.42      140.00      58.80
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.08      140.00      11.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.49      140.00      68.60
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.01      140.00      1.40
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.12      140.00      16.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.01      140.00      1.40
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.37      140.00      51.80
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50      140.00      70.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.49      140.00      68.60
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.01      140.00      1.40

```

Continued on page 3

Work Order : 13139B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	26.53	490.00	0.00	0.00	0.00	516.53
	Totals	26.53	490.00	0.00	0.00	0.00	516.53

&k2S
&k0S