



Warranty Claim Form

Date: 1/7/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT3127T8842726
Transcend 26BHX
Retail Purchase Date: null
Work Started: 12/2/2025
Work Completed: 12/3/2025

Claim Status: Paid
Dealer Work Order #: 13139B
Unit Offline Date: 10/16/2025

Claim #: 954556
Labor: \$308.00
Parts: \$9.24
Shipping: \$0.00
Total: \$317.24

Notes: Sg 12/10/25 650002 - Per production, we do not putty storage areas or inside cabinetry *Please hold all parts for a minimum of 30 days after the claim is paid*

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Improper Installation/Build

Problem: Wall panel next to the shower stall is not finished, jagged finish.

Hours: .2

Cause: Unfinished trim next to shower stall.

Amount: 28.00

Remedy: Used some white silicone to cover the jagged edge of trim after gently sanding the loose finish away.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 660002 Cabinet Doors - Repair Door

Fault Code: Improper Installation/Build

Problem: Both mirrored cabinet doors on each side of the bed rattle badly when opening them.

Hours: .2

Cause: No sealant around back of mirrors to prevent them from rattling when opening.

Amount: 28.00

Remedy: Used clear silicone and ran a bead around the inside edge of the mirrors.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 560049 Lg. Comp./Pass Thru/Kitch./Ent. Ctr. - Adjust/ *Fault Code:* Improper Installation/Build
Repair Door (includes door and frame)

Problem: Deep scratch on the exterior of the bathroom door and on the edge of the same door
there is a large area missing it's finish. *Hours:* .4

Cause: Scratched door and missing chunk out of the side of the door. *Amount:* 56.00

Remedy: Used putty to fill the side and filled the scratch in. *Sublet Repairs:* \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 4

Flat Rate Code: 560037 Baggage - Adjust - Non Slam Latch *Fault Code:* Improper Installation/Build

Problem: All compartment key lock latches do not lock the latched need to be flipped around so they
make it over interior frame of compartment doors. Only the key type. *Hours:* .6

Cause: Improper install of key locks on baggage doors by manufacturer. *Amount:* 84.00

Remedy: Removed the screw on 3 locks that hold the latch in place then flipped them around,
reinstalled screw and tested. They all lock as they should. (3 x 0.2 each) *Sublet Repairs:* \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 5

Flat Rate Code: 620026 Floor Covering - Repair Linoleum Main Floor(per *Fault Code:* Improper Installation/Build
In. ft., including attachments)

Problem: Linoleum flap near stove on slide room is wrinkled upward. *Hours:* .5

Cause: Wrinkled from manufacturer. *Amount:* 70.00

Remedy: Used heat gun to get lino to lay flat as possible. Please also note in case of future
issue. *Sublet Repairs:* \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 6

Flat Rate Code: 230001 Tubes - R&R** - LP Manifold Tubes *Fault Code:* Improper Installation/Build

Problem: The DS LP line from regulator, the green portion that screws onto the bottle is cracked
and part has come off. *Hours:* .3

Cause: Broken LP line end from manufacturer. *Amount:* 42.00

Remedy: Removed the damaged line, installed new line and tested, no leaks. *Sublet Repairs:* \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return</u> <u>Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204	Miscellaneous Part for claim use only		1	1	0.00

240075 REGULATOR 12" PIGTAIL HOSE REGULATOR 12" PIGTAIL HOSE
CONNECTOR ONLY 1/4" INVERTED CONNECTOR ONLY 1/4" INVERTED
MALE FLARE x ACME NUT MALE FLARE x ACME NUT

1 1 9.24