

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13139B

Date In: 05 DEC 25 Author: MGRAY  
Promised Date: 31 DEC 25 Stock No: 11559  
: Year: 2026  
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN  
Address: 11333 COUNTY RD 2 Brand: TRANSCEND XPLOR  
: MIDDLEBURY, IN Model: 26BHX  
Postal/Zip: 46540 Miles/Hrs: 0  
Phone#(res): 888-825-2820 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#: DB: 12/9  
Purchased Date: :  
Delivery Date: :  
InService Date: :  
Serial#: 573TT3127T8842726 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 1 - the ds LP line from W 1020 GRAND  
regulator the green portion that screws  
onto bottle is cracked and part has come  
off  
CAUSE: Broken LP line end from mfg this way  
CORRECTION: Removed the damaged line installed new  
line tested no leaks REQ: .40 WARR  
AUTH: .30  
WARR COMPLAINT: WARRANTY REPAIR 2 - wall panel next to W 1020 GRAND  
shower stall is not finished jagged  
finish  
CAUSE: Unfinished trim next to shower stall  
CORRECTION: I used some white silicone to cover the  
jagged edge of trim after gently sanding  
the loose finish away REQ: .50 WARR  
AUTH: .20  
WARR COMPLAINT: WARRANTY REPAIR 3 - Very deep staple W 1020 GRAND  
holes inside some of the cabinets  
CAUSE: Deep staple holes in cabinetry  
CORRECTION: I used putty to fill all the staple  
holes in cabinets and the walls of  
cabinets REQ: .60 WARR AUTH: DECLINED  
WARR COMPLAINT: WARRANTY REPAIR 4 - Both mirrored W 1020 GRAND  
cabinet doors on each side of the bed  
rattle badly when opening them  
CAUSE: No sealant around back of mirrors to  
prevent them from rattling when opening  
CORRECTION: I used clear silicone and ran a bead

Continued on page 2

Work Order : 13139B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                around the inside edge of the mirrors
                                REQ: .30  WARR AUTH: .20
WARR    COMPLAINT:  WARRANTY REPAIR 5 -Deep scratch on the    W    1020  GRAND
                                exterior of bathroom door and on the
                                edge of the same door their is a large
                                area missing it's finish
                                CAUSE:      Scratched door and missing chunk out of
                                side of door
                                CORRECTION: Used putty to fill the side and filled
                                the scratch in  REQ: .50  WARR AUTH:
                                .40
WARR    COMPLAINT:  WARRANTY REPAIR 6 -All compartment key  W    1020  GRAND
                                lock latches do not lock the latches
                                need to be flipped around so they make
                                it over interior frame of compartment
                                doors Only the key type
                                CAUSE:      Improper install of key locks on baggage
                                doors
                                CORRECTION: I removed the screw on 3 locks that hold
                                the latch in place then I flipped them
                                around reinstalled screw and tested and
                                they all lock as they should  REQ: .40
                                WARR AUTH: .60
WARR    COMPLAINT:  WARRANTY REPAIR 7 - Linoleum flap near  W    1020  GRAND
                                stove on slide room is wrinkled upward
                                CAUSE:      Wrinkled up from mfg
                                CORRECTION: Used heat gun to get lino  to lay flat
                                as possible would like noted in case of
                                future issue  REQ: .40  WARR AUTH: .50

```

```

*****
Job # Part No      Description           PARTS      Bill to  Qty      Price      Total
*****
WARR0 815505010696 20" RV TYPE 1 PIGTAIL  W-1020      1      26.53      26.53

```

```

*****
Job# Lab Code  Description           LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.30      140.00      42.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.38      140.00      53.20
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.01      140.00      1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.42      140.00      58.80
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.08      140.00      11.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.19      140.00      26.60
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.01      140.00      1.40
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.05      140.00      7.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.01      140.00      1.40
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.37      140.00      51.80
ARR06 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.60      140.00      84.00

```

Continued on page 3

Work Order : 13139B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR07 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.49   140.00   68.60
ARR07 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.01   140.00    1.40
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020          26.53    408.80    0.00     0.00    0.00    435.33
      Totals          26.53    408.80    0.00     0.00    0.00    435.33
*****
```

&k2S  
&k0S