

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13146B

Date In:	15 DEC 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11561
:	:	Year:	2026
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	TRANSCEND ONE
:	MIDDLEBURY, IN	Model:	161BH
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 12/15
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT2312T8842972	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Staple holes in      W    1020    GRAND
         cabinets
         CAUSE:      Deep holes throughout unit
         CORRECTION: Used putty to fill the holes  REQUEST:
                     .5
WARR    COMPLAINT:  WARRANTY REPAIR 2 - screen next to table W    1020    GRAND
         is ripped
         CAUSE:      Screen ripped from mfg
         CORRECTION: REM ved spline and screen installed new
                     screen material with spline reinstalled
                     into window  REQUEST: .5
WARR    COMPLAINT:  WARRANTY REPAIR 3 - scrapes in wood and  W    1020    GRAND
         on some ceiling trim throughout the unit
         CAUSE:      Scrapes
         CORRECTION: Used cleaner to remove.ove marks on
                     ceiling trim then filled scraped wood
                     with white putty  REQUEST: .3
WARR    COMPLAINT:  WARRANTY REPAIR 4 - DS decals are        W    1020    GRAND
         bubbled peeling
         CAUSE:      Mfg improper install Order new Door side
                     front decals .I tried pressing out the
                     bubbles to no avail pics taken, blue
                     tape on the 3 decals on ods that need to
                     be ordered
         CORRECTION: .....  REQUEST: 1.0
WARR    COMPLAINT:  WARRANTY REPAIR 5 - ods d cals are        W    1020    GRAND
         bubbled peeling
         CAUSE:      Mfg improper install of decals Order the
```

Continued on page 2

Work Order : 13146B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
front ods decals the word transcend on
ods and the rear decal pics of all
attached
CORRECTION: ..... REQUEST 1.0

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.04  140.00  5.60
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.00  140.00  0.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.46  140.00  64.40
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.00  140.00  0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.00  140.00  0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.48  140.00  67.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.02  140.00  2.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.47  140.00  65.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.03  140.00  4.20

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1020  1.00  0.00  0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W  1020      0.00  350.00  0.00  0.00  0.00  350.00
Totals      0.00  350.00  0.00  0.00  0.00  350.00

```

&k2S
&k0S