

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13146B

Date In:	15 DEC 25	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11561
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	TRANSCEND ONE
:	WISCONSIN RAPIDS, WI	Model:	161BH
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 12/15
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT2312T8842972	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Staple holes in      W    1020    GRAND
         cabinets
         CAUSE:      Deep holes throughout unit
         CORRECTION: Used putty to fill the holes  REQUEST:
                     .5 WARR AUTH: DENIED- GD DOES NOT PUTTY
                     INSIDE CABINETS
WARR    COMPLAINT:  WARRANTY REPAIR 2 - screen next to table W    1020    GRAND
         is ripped
         CAUSE:      Screen ripped from mfg
         CORRECTION: REM ved spline and screen installed new
                     screen material with spline reinstalled
                     into window  REQUEST: .5 WARR AUTH: .20
WARR    COMPLAINT:  WARRANTY REPAIR 3 - scrapes in wood and  W    1020    GRAND
         on some ceiling trim throughout the unit
         CAUSE:      Scrapes
         CORRECTION: Used cleaner to remove.ove marks on
                     ceiling trim then filled scraped wood
                     with white putty  REQUEST: .3 WARR
                     AUTH: .10
WARR    COMPLAINT:  WARRANTY REPAIR 4 - DS decals are        W    1020    GRAND
         bubbled peeling
         CAUSE:      Mfg improper install Order new Door side
                     front decals .I tried pressing out the
                     bubbles to no avail pics taken, blue
                     tape on the 3 decals on ods that need to
                     be ordered Decals have air bubbles in
                     them. Both sides of unit.
         CORRECTION: ..... Poked holes in decals to get air
```

Continued on page 2

Work Order : 13146B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                out. .... REQUEST: 1.0 WARR AUTH: 1
                                HOUR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - ods d cals are      W    1020    GRAND
                                bubbled peeling
                                CAUSE:  Decals bubbling ods  Mfg improper
                                install of decals  Order the front ods
                                decals the word transcend on ods and the
                                rear decal pics of all attached
                                CORRECTION: Was able to work out air bubbles by
                                poking small holes in them and working
                                the air out. ....

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty    Price    Total
*****
WARR0 822091105 DIE CUT SIDE #27 RH XPLOR 2 W-1020      1     18.58    18.58
WARR0 822012118 DIE CUT TRANSCEND SIDE #34 W-1020      1      8.26     8.26
WARR0 82202362  DIE CUT SIDE #41 TRANSCEND W-1020      1     23.36    23.36
WARR0 822091104 DIE CUT SIDE #27 LH XPLOR 2 W-1020      1     18.58    18.58
WARR0 82202117  DIE CUT TRANSCEND SIDE #34 W-1020      1      8.26     8.26
WARR0 822012363 DIE CUT SIDE #42 TRANSCEND W-1020      1     23.36    23.36
WARR0 822091086 DIE CUT SMALL TRANSCEND LEG W-1020      1     21.22    21.22

```

```

*****
Job#  Lab Code  Description           LABOUR    Mech Bill to   Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.01   140.00     1.40
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00   140.00     0.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.46   140.00    64.40
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.20   140.00    28.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00   140.00     0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.10   140.00    14.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00   140.00     0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.48   140.00    67.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.02   140.00     2.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.47   140.00    65.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.03   140.00     4.20
ARR04 WARR      MANUFACTURER WARRANTY TD W-1020      0.34   140.00    47.60
ARR05 WARR      MANUFACTURER WARRANTY TD W-1020      0.50   140.00    70.00
ARR04 WARR      MANUFACTURER WARRANTY TD W-1020      0.16   140.00    22.40

```

```

*****
Job #  Excode   Description           EXTRAS           bill to   Qty    Price    Total
*****
ARR01 SSE       SHOP SUPPLIES - EXTERNAL W-1020      1.00     0.00     0.00
ARR04 FRT       FREIGHT FOR JOB WARR04 W-1020      1.00    23.55    23.55
ARR05 FRT       FREIGHT FOR INV. 1526651 W-1020      1.00    19.01    19.01
ARR05 FRT       FREIGHT FOR INV 1527624 W-1020      1.00    18.31    18.31

```

Continued on page 3

Work Order : 13146B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	121.62	387.80	0.00	60.87	0.00	570.29
	Totals	121.62	387.80	0.00	60.87	0.00	570.29

&k2S
&k0S