

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13146B

Date In:	15 DEC 25	Author:	MGRAY
Promised Date:	31 MAY 26	Stock No:	11561
:	:	Year:	2026
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	TRANSCEND ONE
:	MIDDLEBURY, IN	Model:	161BH
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 12/15
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT2312T8842972	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Staple holes in          W    1020    GRAND
        cabinets
        CAUSE:       Deep holes throughout unit
        CORRECTION:  Used putty to fill the holes  REQUEST:
        .5 WARR AUTH: DENIED- GD DOES NOT PUTTY
        INSIDE CABINETS
WARR    COMPLAINT:  WARRANTY REPAIR 2 - screen next to table W    1020    GRAND
        is ripped
        CAUSE:       Screen ripped from mfg
        CORRECTION:  REM ved spline and screen installed new
        screen material with spline reinstalled
        into window  REQUEST: .5 WARR AUTH: .20
WARR    COMPLAINT:  WARRANTY REPAIR 3 - scrapes in wood and W    1020    GRAND
        on some ceiling trim throughout the unit
        CAUSE:       Scrapes
        CORRECTION:  Used cleaner to remove.ove marks on
        ceiling trim then filled scraped wood
        with white putty  REQUEST: .3 WARR
        AUTH: .10
WARR    COMPLAINT:  WARRANTY REPAIR 4 - DS decals are          W    1020    GRAND
        bubbled peeling
        CAUSE:       Mfg improper install Order new Door side
        front decals .I tried pressing out the
        bubbles to no avail pics taken, blue
        tape on the 3 decals on ods that need to
        be ordered Decals have air bubbles in
        them. Both sides of unit.
        CORRECTION:  ..... Poked holes in decals to get air
```

Continued on page 2

Work Order : 13146B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                out. .... REQUEST: 1.0 WARR AUTH: 1
                                HOUR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - ods d cals are          W    1020    GRAND
                                bubbled peeling
                                CAUSE:  Decals bubbling ods  Mfg improper
                                install of decals  Order the front ods
                                decals the word transcend on ods and the
                                rear decal pics of all attached
                                CORRECTION: Was able to work out air bubbles by
                                poking small holes in them and working
                                the air out. ....

```

```

*****
Job # Part No   Description                PARTS                Bill to   Qty    Price    Total
*****
WARR0 822091105 DIE CUT SIDE #27 RH XPLO 2 W-1020          1    18.58    18.58
WARR0 822012118 DIE CUT TRANSCEND SIDE #34 W-1020          1     8.26     8.26
WARR0 82202362  DIE CUT SIDE #41 TRANSCEND W-1020          1    23.36    23.36
WARR0 822091104 DIE CUT SIDE #27 LH XPLO 2 W-1020          0    18.58     0.00
WARR0 82202117  DIE CUT TRANSCEND SIDE #34 W-1020          0     8.26     0.00
WARR0 822012363 DIE CUT SIDE #42 TRANSCEND W-1020          0    23.36     0.00
WARR0 822091086 DIE CUT SMALL TRANSCEND LEG W-1020         0    21.22     0.00
WARR0 822091104 DIE CUT SIDE #27 LH XPLO 2 W-1020          1    18.58    18.58
WARR0 82202117  DIE CUT TRANSCEND SIDE #34 W-1020          1     8.26     8.26
WARR0 822012363 DIE CUT SIDE #42 TRANSCEND W-1020          1    23.36    23.36
WARR0 822091086 DIE CUT SMALL TRANSCEND LEG W-1020         1    21.22    21.22

```

```

*****
Job#   Lab Code   Description                LABOUR    Mech Bill to   Hrs    Rate    Total
*****
ARR01 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.01   140.00    1.40
ARR01 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.00   140.00    0.00
ARR01 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.46   140.00   64.40
ARR02 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.20   140.00   28.00
ARR02 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.00   140.00    0.00
ARR03 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.10   140.00   14.00
ARR03 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.00   140.00    0.00
ARR04 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.48   140.00   67.20
ARR04 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.02   140.00    2.80
ARR05 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.47   140.00   65.80
ARR05 Z992       MISC LABOUR CODE (WARR HOD W-1020          0.03   140.00    4.20
ARR04 WARR       MANUFACTURER WARRANTY TD W-1020          0.34   140.00   47.60
ARR05 WARR       MANUFACTURER WARRANTY TD W-1020          0.50   140.00   70.00
ARR04 WARR       MANUFACTURER WARRANTY TD W-1020          0.16   140.00   22.40

```

```

*****
Job #   Excode    Description                EXTRAS                bill to   Qty    Price    Total
*****
ARR01   SSE       SHOP SUPPLIES - EXTERNAL W-1020          1.00    0.00    0.00

```

Continued on page 3

Work Order : 13146B

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR04  FRT      FREIGHT FOR JOB WARR04    W-1020    1.00    23.55    23.55
ARR05  FRT      FREIGHT FOR INV. 1526651  W-1020    1.00    19.01    19.01
ARR05  FRT      FREIGHT FOR INV 1527624  W-1020    1.00    18.31    18.31

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
W      1020        121.62    387.80     0.00     60.87     0.00    570.29

      Totals      121.62    387.80     0.00     60.87     0.00    570.29

```

&k2S

&k0S