

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13163B

Date In: 30 JAN 26 Author: MGRAY
Promised Date: 31 DEC 26 Stock No: 11565
: Year: 2026
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: FLAGSTAFF E-PRO
: CHICAGO, IL Model: 17LE
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 1/30
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 5ZT2FSJCXT3040342 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - Water pump does not W 1021 FORES
come on
CAUSE: The connection on power to fuse to pump
both were not allowing power through
CORRECTION: I removed panel to access pump removed 2
screws holding pump into place cut the
fuse wire out then restriped the two
power wires and connected turned switch
to pump on it now has power. I then
wired the 10 amp fuse between the 2
wires after restriping both ends of that
wire tested powers on once again then I
recrimped both and tested it is powering
on . I screwed the pump back down and
put panel back In to place REQUEST .5
WARR COMPLAINT: WARRANTY REPAIR 2 - wall panel next to W 1021 FORES
the refer has popped away from the stud
CAUSE: The panel was loose I secured panel but
large holes that look terrible filled
are on panels edge . We do not have any
of this color in stock tried 3 times
matching up the colors to no avail
ORDER A NEW BATTEN STRIP WOOD GRAIN
LIGHT TAN COLORED ALSO IF A FEW MORE
BSTTRN CAN BE ORDERED WITH THIS TO SAVE
ON SHIPPING , THIS IS A COMMON COLOR AND
WE SHOULD HAVE THIS IN STOCK
CORRECTION: REQUEST :1.0

Continued on page 2

Work Order : 13163B

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 3 - The fabric lp cover W   1021   FORES
        has many splits in it
        CAUSE:      Splits in fabric Please order new
                   single 20 pound black fabric lp cover
        CORRECTION: ..... REQUEST .5
*****
```

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992    MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR01 Z992    MISC LABOUR CODE (WARR HOD W-1021  0.00  140.00   0.00
ARR02 Z992    MISC LABOUR CODE (WARR HOD W-1021  0.00  140.00   0.00
ARR02 Z992    MISC LABOUR CODE (WARR HOD W-1021  0.01  140.00   1.40
ARR02 Z992    MISC LABOUR CODE (WARR HOD W-1021  0.49  140.00  68.60
ARR03 Z992    MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE     SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W    1021      0.00  210.00  0.00  0.00  0.00  210.00
*****
Totals      0.00  210.00  0.00  0.00  0.00  210.00
*****
```

&k2S
&k0S