

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2566095
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2FSJCXT3040342
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010G
 ITEM # FLTE17LE
 DEALER RO # 13163B
 CLAIM START DATE 01/30/2026
 CLAIM END DATE 03/03/2026

Labor rate: \$140.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 40-196-24-11-001297 Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2026-01-30 10:46:26 :: Complaint: Water pump does not come on. Cause: The connection on power to fuse to pump, both were not allowing power through. Correction: Removed the panel to access pump, removed 2 screws holding pump into place, cut the fuse wire out then restriped the two power wires and connected, turned switch to pump on and it now has power. I then wired 10 amp fuse between the 2 wires after restriping both ends of that wire, tested powers on once again and then recrimped both and tested it is powering on. I screwed the pump back down and put panel back in to place.
 Additional Note : greeneway@dealer-advisors.com, 2026-01-30 10:49:53 :: Unsure on correct labor code.

Model# 1	Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial# 1	Appr Hrs	0.50	Appr Labor Amt \$70.00

Notes

Hello, the labor time submitted to Forest River has been reviewed and reduced based on the photos and description provided as well as the most applicable flat rate code. Thank you Authorized

Labor

Line# 2 **Operation Code** **Operational Description**
 30-100-12-00-001049 Cabinet End Panel - Interior/Cabinetry/Resecure or Tighten/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2026-01-30 10:51:34 :: Complaint: Wall panel next to refer has popped away from the stud. Cause: The panel was loose. Correction: Secured the panel but there were large holes that look terrible, filled on panels edge but we do not have any of this color in stock, tried 3 times to match up the colors to no avail. Need to order a new batten strip, wood grain light tan colored. Additional Note : greeneway@dealer-advisors.com, 2026-01-30 10:52:09 :: Time includes attempted repair and replacing the batten strip along with resecuring the wall panel.

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$140.00
Serial#	Appr Hrs	1.00	Appr Labor Amt \$140.00

Notes

Hello, the repair code has been updated to a more appropriate one based on the root cause of the issue.

Part

Line# 1 **Item #** **Description**
 F100337708 BATTEN - 6A-1: WOODGRAIN - SEDONAWOOD - 7/8" X 8' - V# 47082897 | X

Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$2.83	Sub Freight	\$11.70
Appr Qty	1.00	Appr Dlr Price	\$2.83	Appr Freight	\$11.70

Notes

Line# 2	Item #		Description			
	F100270074		SPECIAL PACKAGING - MOLDINGS 9' OR LESS (INCLUDING FASCIA, BATTEN, STILES & EXTERIOR MOLDINGS)			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$13.00	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$0.00	Appr Freight	\$13.00

Notes

Hello, Forest River respectfully does not pay for markup on special packaging and or Freight cost. Special package cost/Freight cost Adjusted to \$13.00 made in processing. Thank you

Line# 3	Item #		Description			
	F100410860		PANELING - PFL: LAUAN - SEDONAWOOD - 1/8" X 4' X 8' - V# 45210502 N			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$57.06	Sub Freight	\$100.00
	Appr Qty	1.00	Appr Dlr Price	\$57.06	Appr Freight	\$100.00

Notes

Line# 4	Item #		Description			
	F100035225		SPECIAL PACKAGING - PANELING OR BACKSPLASH FULL PANELS (5 PER BOX)			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$29.00	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$0.00	Appr Freight	\$29.00

Notes

Hello, Forest River respectfully does not pay for markup on special packaging and or Freight cost. Special package cost/Freight cost Adjusted to \$29.00 made in processing. Thank you

Labor

Line# 3	Operation Code		Operational Description			
	50-134-01-00-001454		LP Bottle Cover - LP Gas/LP Gas System/Replace/No Tread Code			
	Complaint, Cause, Correction					
	Original Note : greenway@dealer-advisors.com, 2026-01-30 10:52:48 :: Complaint: The fabric LP cover has many splits in it. Cause: Splits in fabric. Correction: Replace black fabric LP cover.					
	Model#		Dlr Sub Hrs	0.50	Sub Labor Amt	\$70.00
	Serial#		Appr Hrs	0.10	Appr Labor Amt	\$14.00

Notes

Hello, the labor time submitted to Forest River has been reviewed and reduced based on the photos and description provided as well as the most applicable flat rate code. Thank you

Part

Line# 1	Item #		Description			
	F100114243		LP TANK COVER - 2C-4: SINGLE COVER FOR 20LB TANK, VINYL - BLACK - V# 20# SINGLE COVER BLK X			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$17.59	Sub Freight	\$19.56
	Appr Qty	1.00	Appr Dlr Price	\$17.59	Appr Freight	\$19.56

Notes

Submitted	Labor Amt	\$280.00	Approved	Labor Amt	\$224.00
	Parts & Freight	\$263.34		Parts & Freight	\$250.74
	Total	\$543.34		Total	\$474.74

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.