

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2566112
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2FSJC3T3040344
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	010 / 010G
Labor rate:	\$140.00	ITEM #	FLTE17LE
OWNER INFORMATION		DEALER RO #	13171B
		CLAIM START DATE	01/30/2026
		CLAIM END DATE	02/19/2026

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	50-134-01-00-001454	LP Bottle Cover - LP Gas/LP Gas System/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-01-30 10:54:57 :: Complaint: the 20# black fabric lp cover has slits in the fabric. Cause: Cracked fabric. Correction: Replace fabric LP cover.			
Model#	Dlr Sub Hrs	0.70	Sub Labor Amt	\$98.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$14.00

Notes

Hello, the labor time submitted to Forest River has been reviewed and reduced based on the photos and description provided as well as the most applicable flat rate code. Thank you

Part

Line# 1	Item #	Description			
	F100114243	LP TANK COVER - 2C-4: SINGLE COVER FOR 20LB TANK, VINYL - BLACK - V# 20# SINGLE COVER BLK X			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$17.59	Sub Freight \$19.59
	Appr Qty	1.00	Appr Dlr Price	\$17.59	Appr Freight \$19.59

Notes

Submitted	Labor Amt	\$98.00	Approved	Labor Amt	\$14.00
	Parts & Freight	\$37.18		Parts & Freight	\$37.18
	Total	\$135.18		Total	\$51.18

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.